Goldman Arlington Apartment Official Violations

Code Visit Violations

Since purchasing the property, on at least 33 occasions Arlington Code Compliance has been called to Goldman's property and issued official notice of violations for a range of issues related to raw sewage, air conditioning problems, roach infestations and other issues.

Date of Violation	Type of Violation
10/17/2013	Raw Sewage
10/22/2013	Raw Sewage
10/24/2014	Clogged Bathtub
12/5/2014	Heat
12/17/2014	Debree
2/9/2015	Bed Bugs
3/23/2015	Fire
3/23/2015	Stove
4/30/2015	Debree
7/24/2015	Water Leak
8/7/2015	Unclean Premises
9/2/2015	Unclean Premises
12/21/2015	Raw Sewage
1/11/2016	Raw Sewage
2/29/2016	Hole in Roof
3/1/2016	Lighting
5/25/2016	Bed Bugs
6/7/2016	Debree
10/19/2016	A/C
9/20/2017	A/C

12/28/2017	Heating
1/10/2018	Heating
5/25/2018	Mold
6/19/2018	Raw sewage
7/25/2018	Raw Sewage
8/27/2018	Roach Infestation
2/4/2019	Roach Infestation
2/11/2019	Raw Sewage
5/2/2019	Roach Infestation
5/31/2019	Water Leak
6/26/2019	Bed Bugs
7/19/2019	Failure to attend
11/6/2019	AC/Heat

Annual Inspection Violations:

Since purchasing the property, annual inspections of the property by the city of Arlington have revealed 272 violations for Goldman's properties:

Year	Number of Violations
2014	65
2015	141
2016	45
2016	3
2018	12
2019	6



Address: 408 N FIELDER ROAD BLDG 01

Violation: Raw Sewage - Exterior Date Reported: Wednesday October 16, 2013

Assigned CCO: Joe Rodriguez Proactive? Code Ranger? Print Date: Monday May 11, 2020 Complaint/Concern Number: 13-555673-CODE

Police PRA: 133 Police Beat: 330 Council District: 4 Mapsco Page: 82F

Concern Description

Sewage water running down the curb. The building with the problem is the far north building.

Code Compliance Officer Inspection Data

DATE: 10/17/2013 CCO: Joe Rodriguez

RESULT: Notice of Violation

COMMENTS: JMT left a message with Bill Brown at 6560 regarding the sewage overflow into the storm drain. This is a new owner and he does have a crew on site Service Response Team (SRT) 972 263-0142. Issued NOV to the owner and will return tomorrow to re-inspect, located at BDG 20. JR

DATE: 10/16/2013 CCO: Sergio Erazo RESULT: Call Received COMMENTS:

DATE: 10/18/2013 CCO: John Taylor RESULT: Owner Abated COMMENTS: Far North building is # 20.

Additional Comments or Notes

Date: 10/18/2013 Made By: Joe Rodriguez

EMAIL from Craig Goldman craig@arlingtonvillageapartments.com regarding sewage overflow 10-17-

13

Gentlemen:

I just wanted to let you know that Sevice Response Team has been at our property for the last three hours and they are finishing up their work. They have determined by viewing our piping with their cameras that the problem is not with broken pipe but meerly grease that has built up in the pipes over years of time that has caused the backup in our pipes. They have spent the last few hours hydropumping to clean them out and they feel certain this will not happen again in the near future. We are more than likely going to sign a contract with them to have them hydropump more actively to prevent this from happening again.

As I mentioned to you both, we do not want this to happen again and we are committed to doing all that we can to prevent this from happening again. It is a major problem our friends before us left us with that we now feel we know we can prevent from happening in the future.

Thanks for your cooperation and understanding.

Craig

END OF REPORT COMPLIANCE DATE: Oct 18 2013 3:32PM



Address: 408 N FIELDER ROAD BLDG 01

Violation: Raw Sewage - Exterior Date Reported: Tuesday October 22, 2013

Assigned CCO: Joe Rodriguez Proactive? Code Ranger? Print Date: Monday May 11, 2020 Complaint/Concern Number: 13-560424-CODE

Police PRA: 133 Police Beat: 330 Council District: 4 Mapsco Page: 82F

Concern Description

Anon stated raw sewage coming out of this complex is running down the street and into the park pond

Code Compliance Officer Inspection Data

DATE: 10/22/2013 CCO: Joe Rodriguez RESULT: Issue Citation COMMENTS: 10-22-13 Issued CX 000674407-1 for U-P (raw sewage). JR

DATE: 10/22/2013 CCO: Maria Gamez RESULT: Call Received COMMENTS:

DATE: 10/24/2013 CCO: John Taylor RESULT: Owner Abated COMMENTS: No violations found.

Additional Comments or Notes

END OF REPORT COMPLIANCE DATE: Oct 24 2013 3:42PM



Address: 408 N FIELDER ROAD SUITE O225

Violation: Hazardous Plumbing Date Reported: Wednesday October 22, 2014

Assigned CCO: Ron Plute Proactive? No Code Ranger? Print Date: Monday May 11, 2020 Complaint/Concern Number: 14-747360-CODE

Police PRA: 133 Police Beat: 330 Council District: 4 Mapsco Page: 82F

Concern Description

Bath tub clogged up water won't drain.

Code Compliance Officer Inspection Data

DATE: 10/24/2014 CCO: Ron Plute

RESULT: Notice of Violation

COMMENTS: Contacted complainant via phone and left a message, and also left BC on door when I stopped by. I will leave a NOV for the office based of the complaint.RP

DATE: 10/22/2014 CCO: Sergio Erazo RESULT: Call Received COMMENTS:

DATE: 10/27/2014 CCO: Ron Plute RESULT: Owner Abated COMMENTS: Received call from the tennant stating that the property has been repaired.RP

Additional Comments or Notes

END OF REPORT COMPLIANCE DATE: Oct 27 2014 10:22AM



Address: 408 N FIELDER ROAD BLDG 01

Violation: No Heat Date Reported: Tuesday December 2, 2014

Assigned CCO: Ron Plute Proactive? No Code Ranger? Print Date: Monday May 11, 2020 Complaint/Concern Number: 14-770576-CODE

Police PRA: 133 Police Beat: 330 Council District: 4 Mapsco Page: 82F

Concern Description

Village Apts

Building 14 #166

No heat in the apartment for over 6 days.

Code Compliance Officer Inspection Data

DATE: 12/05/2014 CCO: Ron Plute

RESULT: Notice of Violation

COMMENTS: Contacted the complainant and left a message. Spoke to management and they were able to provide me with proof that theunit was repaired on 11/26 and 11/17. The owner is going to email me the invoice from the HVAC contractor that repaired the unit.RP

DATE: 12/02/2014 CCO: Rosalyn Guerrero RESULT: Call Received COMMENTS:

DATE: 12/17/2014 CCO: Ron Plute RESULT: Owner Abated COMMENTS: The heat has been repaired.RP

Additional Comments or Notes

END OF REPORT

COMPLIANCE DATE: Dec 17 2014 9:09AM



Address: 408 N FIELDER ROAD BLDG 01

Violation: Unclean Premises Date Reported: Thursday December 11, 2014

Assigned CCO: Ron Plute Proactive? No Code Ranger? Print Date: Monday May 11, 2020 Complaint/Concern Number: 14-776768-CODE

Police PRA: 133 Police Beat: 330 Council District: 4 Mapsco Page: 82F

Concern Description

Anon caller trash on the sidewalk at least three to four times a week.

Code Compliance Officer Inspection Data

DATE: 12/17/2014 CCO: Ron Plute RESULT: Notice of Violation

COMMENTS: Upon inspection there was an abundance of furniture and trash around the dumpster enclosure.RP

DATE: 12/11/2014 CCO: Wynnetra Yansen RESULT: Call Received COMMENTS:

DATE: 01/23/2015 CCO: Ron Plute RESULT: Owner Abated COMMENTS: Upon inspection the property was clean of furniture.RP

Additional Comments or Notes

END OF REPORT COMPLIANCE DATE: Jan 23 2015 9:59AM



Address: 408 N FIELDER ROAD SUITE J133

Violation: Insect / Rodent Infestation Date Reported: Tuesday February 3, 2015

Assigned CCO: Ron Plute Proactive? No Code Ranger? Print Date: Monday May 11, 2020 Complaint/Concern Number: 15-727436-CODE

Police PRA: 133 Police Beat: 330 Council District: 4 Mapsco Page: 82F

Concern Description

states that her apartment has bed bugs. follow up

Code Compliance Officer Inspection Data

DATE: 02/09/2015 CCO: Ron Plute RESULT: Notice of Violation COMMENTS: Left NOV with Management.RP

DATE: 02/03/2015 CCO: Lisa Mornes RESULT: Call Received COMMENTS:

DATE: 03/16/2015 CCO: Victor AlfaroRESULT: Owner AbatedCOMMENTS: Property was finally treaded. Received an invoice from Envirotrol Pest Managemeet Systems.

Additional Comments or Notes

Date: 03/02/2015 Made By: Victor Alfaro

Made contact with comp. She stated that they sent someone to the unit but she sent them away to reschedule. She stated that they have not reschedule her.

I meet with management at the property they stated that the tenant was rude and did not allow the pest control to enter the unit and she would not leave the unit so that the pest control could treat the property. I also received an invoice from management that pest control gave them. In the notes the tech entered 133-Resident did not want to leave the unit. Resident had attitude. A copy of the the work order is attached.

I informed management that the unit had to be treated and that they should reschedule the treatment. I attempted to contact the comp via phone to explain to her that in order for the treatment to work she would need to do what the pest control tech ask her to do. The comp did not pick up the phone and I left a message stated to call me back.

Date: 03/11/2015 Made By: Victor Alfaro

Went to the management office the manager on site stated that pest control will be out on Wed. She also stated that pest control went to the unit on 3-10-15 and it was not prepared per invoice attached.

I contact the comp informed her that on Wed pest control was going to go and she need to have everything prep for pest control. I also informed her that pest control attempted to stray on 3-10-15 but could not due to the apt not being prep. She was not happy and was frustrated.

END OF REPORT COMPLIANCE DATE: Mar 16 2015 11:13AM



Address: 408 N FIELDER ROAD SUITE 1118

Violation: Inadequate Sanitation Date Reported: Monday March 23, 2015

Assigned CCO: Lesley Mills Proactive? No Code Ranger? Print Date: Monday May 11, 2020 Complaint/Concern Number: 15-754862-CODE

Police PRA: 133 Police Beat: 330 Council District: 4 Mapsco Page: 82F

Concern Description

Spoke to manager she stated that the unit does not have a functioning stove. VA

Code Compliance Officer Inspection Data

DATE: 03/23/2015 CCO: Victor Alfaro RESULT: Notice of Violation COMMENTS:

DATE: 03/23/2015 CCO: Victor Alfaro RESULT: Call Received COMMENTS:

DATE: 04/06/2015 CCO: Victor Alfaro RESULT: Owner Abated COMMENTS: The stove has been repaired accordingto the tenant

Additional Comments or Notes

END OF REPORT COMPLIANCE DATE: Apr 6 2015 4:14PM



Address: 408 N FIELDER ROAD SUITE I118

Violation: Fire Report Date Reported: Thursday March 19, 2015

Assigned CCO: Ron Plute Proactive? No Code Ranger? Print Date: Monday May 11, 2020 Complaint/Concern Number: 15-753037-CODE

Police PRA: 133 Police Beat: 330 Council District: 4 Mapsco Page: 82F

Concern Description

While moving in apt a box was set on the stove and had inadvertantly turn the right front burner on and started fire

Code Compliance Officer Inspection Data

DATE: 03/23/2015 CCO: Victor Alfaro RESULT: Notice of Violation COMMENTS:

DATE: 03/19/2015 CCO: Kelly Marvel RESULT: Call Received COMMENTS:

DATE: 04/06/2015 CCO: Victor AlfaroRESULT: Owner AbatedCOMMENTS: Inspected the property with CCO Trotter at the time of inspection all the repairs were made.

Additional Comments or Notes

END OF REPORT COMPLIANCE DATE: Apr 6 2015 4:12PM



Address: 408 N FIELDER ROAD SUITE Q261

Violation: Unclean Premises Date Reported: Thursday April 30, 2015

Assigned CCO: Lesley Mills Proactive? No Code Ranger? Print Date: Monday May 11, 2020 Complaint/Concern Number: 15-779543-CODE

Police PRA: 133 Police Beat: 330 Council District: 4 Mapsco Page: 82F

Concern Description

RECEIVED A CALL ABOUT ENTIRE PROPERTY HAS UNCLEAN PREMISES THROUGHOUT

Code Compliance Officer Inspection Data

DATE: 04/30/2015 CCO: Lesley Mills RESULT: Notice of Violation COMMENTS: NOV HANDED TO OFFICE AND PLACED ON DOOR FOR UP OF CHAIRS, WORKOUT MATERIAL, TRASH, ICE CHEST ON FRONT PORCH AREA

DATE: 04/30/2015 CCO: Lesley Mills RESULT: Call Received COMMENTS:

DATE: 05/13/2015 CCO: Lesley Mills RESULT: Owner Abated COMMENTS: ALL VIOLATIONS HAVE BEEN CORRECTED

Additional Comments or Notes

END OF REPORT

COMPLIANCE DATE: May 13 2015 12:00AM



Address: 408 N FIELDER ROAD BLDG 01

Violation: Water Leakage Date Reported: Thursday July 23, 2015

Assigned CCO: Lesley Mills Proactive? No Code Ranger? Print Date: Monday May 11, 2020 Complaint/Concern Number: 15-835767-CODE

Police PRA: 133 Police Beat: 330 Council District: 4 Mapsco Page: 82F

Concern Description

Arlington Village #42

Water leak from the ceiling. Bed bug infestation in the apartment.

Code Compliance Officer Inspection Data

DATE: 07/24/2015 CCO: Lesley Mills RESULT: Notice of Violation

COMMENTS: NOV HANDED TO MANAGER AND RESIDENT FOR WATER LEAK IN LEAVINGROOM CEILING.

DATE: 07/23/2015 CCO: Rosalyn Guerrero RESULT: Call Received COMMENTS:

DATE: 08/03/2015 CCO: Lesley Mills RESULT: Reinspection COMMENTS: RESIDENT WAS NOT HOME, CALLED AND HE WANTS TO MEET ME ON 8/6/15 BUT HE STATED NOTHING HAS BEEN DONE IN HIS UNIT

DATE: 08/12/2015 CCO: Lesley Mills RESULT: Owner Abated COMMENTS: ALL VIOLATIONS HAVE BEEN CORRECTED

Additional Comments or Notes

END OF REPORT



Address: 408 N FIELDER ROAD BLDG 01

Violation: Raw Sewage - Exterior Date Reported: Monday December 21, 2015

Assigned CCO: David Engel Proactive? No Code Ranger? Print Date: Friday December 20, 2019 Complaint/Concern Number: 15-947094-CODE

Police PRA: 133 Police Beat: 330 Council District: 1 Mapsco Page: 82F

Concern Description

Village Apartments

Anon reporting raw sewage that is flowing in the parking lot and into the street

Code Compliance Officer Inspection Data

DATE: 12/21/2015 CCO: Victor AlfaroRESULT: Notice of ViolationCOMMENTS: Water is flowing in to the street and it smells like raw. Water is flowing from out of the building.

DATE: 12/21/2015 CCO: Phoebe Ramirez RESULT: Call Received COMMENTS:

DATE: 12/28/2015 CCO: David Engel RESULT: Owner Abated COMMENTS: per cco va the site was cleaned

Additional Comments or Notes

Date: 12/21/2015 Made By: Victor Alfaro

Spoke to the manager about the property and handed her NOV and sewage letter. She stated that they are aware of the situation and had Service Response Team out on the 18th. Water is flowing into the street and I informed the manager that the issue had to be resolved and we would be back in 24hrs. Service Response Team was on site.

END OF REPORT

COMPLIANCE DATE: Dec 28 2015 8:22AM



Address: 408 N FIELDER ROAD BLDG 20

Violation: Raw Sewage - Exterior Date Reported: Monday January 11, 2016

Assigned CCO: David Engel Proactive? No Code Ranger? Print Date: Thursday December 26, 2019 Complaint/Concern Number: 16-881713-CODE

Police PRA: 133 Police Beat: 330 Council District: 1 Mapsco Page: 82F

Concern Description

reporting raw sewage coming out of the main line along building 20, located on SW of property, and it is running down to the creek. Apt management has been notified

Code Compliance Officer Inspection Data

DATE: 01/11/2016 CCO: Lesley Mills RESULT: Notice of Violation COMMENTS: NOV issued to officer for raw sewage on back building.

DATE: 01/11/2016 CCO: Modesto Caldera Jr RESULT: Call Received COMMENTS:

DATE: 01/13/2016 CCO: Lesley Mills RESULT: Owner Abated COMMENTS: ALL VIOLATIONS HAVE BEEN CORRECTED

Additional Comments or Notes

Date: 01/11/2016 Made By: Lesley Mills

Spoke to Service Response Team member Clint about the property he stated that they are making repairs to the property and it should be complete today. Contacted Environmental rep 8174696550 that stated they will send a person to the property.

END OF REPORT COMPLIANCE DATE: Jan 13 2016 3:33PM



Address: 408 N FIELDER ROAD BLDG 14

Violation: Exterior Lighting Violation Date Reported: Tuesday March 1, 2016

Assigned CCO: David Engel Proactive? No Code Ranger? Print Date: Tuesday May 12, 2020 Complaint/Concern Number: 16-920768-CODE

Police PRA: 133 Police Beat: 330 Council District: 1 Mapsco Page: 82F

Concern Description

LIGHT TRESPASS COMPLAINT. JR

Code Compliance Officer Inspection Data

DATE: 03/01/2016 CCO: Joe Rodriguez RESULT: Monitor

COMMENTS: 3/1/16 This complaint came from an adjacent property located at 600 Matthews Dr. Per the resident 408 N Fielder Rd (NFR) recently replaced some exterior lighting for security measures. In taking this step there has been some light trespassing issues brought to our attention. On the evening of 2/26/16 I was able to take measurements of the height of the light fixtures. These lights are under 20' and do not exceed maxima height allowed per UDC 5.4.9. (F) 2.3, the distance from the light fixture is approximately 165' to 600 Matthews Dr. which is beyond the 100' allowed in the UDC. With that said I was able to document and attach a power point from 2/26/16 which shows two factors that would cause (NFR) to be in violation, 1st being the direction the housing is set at. Currently there is room for the property to adjust the light housing further in a downward position to help better project the light away from 600 Matthews Dr. 2nd there is the lack of shields attached to the light fixtures which could help deflect light away from 600 Matthews. These two steps can be taken by (NFR) to comply with the light trespass violation. Today CCO LM contacted the owner via phone and the owner agreed to adjust the lights at this building, I will be out Thursday morning to re-inspect the lighting situation on this property, as of now per JMT a NOV has not been issued to (NFR). I was also contacted by 600 Matthews requesting a status update, and I explained to the citizen there were steps we were taking and the owner has been made aware of this issue and that there will be a re-inspection conducted on Thursday morning. JR

DATE: 03/03/2016 CCO: Joe Rodriguez RESULT: Monitor

COMMENTS: 3/3/16 I came by early pre-dawn and was able to observe different lighting violations and attached a pwr point to AMANDA. Later in the morning CCOs MIlls, Eraso & myself came to the property to meet the owner regarding my earlier observations. The owner explained that the lights are new and in an attempt not to void any possible warranties his electrician would be conducting the adjustments today. I did

also ask if there were staff members on site that could conduct an evening exterior non-tenant controlled lighting inspection of the grounds. The owner stated that he has a security company that patrols and would have them conduct this inspection and identify any and all inoperable light fixtures. Per instructions from JMT NOV will not be issued at this time and the owner has been given a week to remedy all lighting violations. JR

DATE: 03/15/2016 CCO: Joe Rodriguez

RESULT: Notice of Violation

COMMENTS: 3/15/16 I conducted a pre-dawn exterior lighting inspection at 408 N Fielder Rd. On this date I observed multiple exterior lighting failures. On 3/3/16 I spoke with the property owner and explained to him that I had already observed some light failures. I also asked if he had some staff that would be able to conduct an evening inspection and identify the buildings in violation, he stated that he would have his security patrol look for the lighting failures. JR

DATE: 03/01/2016 CCO: Joe Rodriguez RESULT: Call Received COMMENTS:

DATE: 03/22/2016 CCO: Joe Rodriguez

RESULT: Notice of Violation

COMMENTS: 3/22/16 The NOV had been hand delivered on 3/15/16 to staff employee Yamie due to the fact that the property owner was away at the time of my arrival and wasn't expected for another hour. Today I conducted another exterior lighting picture however the NOV compliance date is still in effect until 3/29/16. I did document my observations and will attach them into AMANDA. JR

DATE: 03/30/2016 CCO: Joe Rodriguez

RESULT: Reinspection

COMMENTS: 3/30/16 I came by the property this morning pre-dawn and was able to observe the building lights had been repaired, however the street lamp addressed between building 12 & 13 was still an issue. That said on todays visit I also observed more of the street lamps in violation. I will go by the office today and meet with the management and inquire when they will be completed. JR

DATE: 10/05/2016 CCO: Joe Rodriguez RESULT: Reinspection

COMMENTS: 10/5/16 The evening of NNO 10/4/16 myself and SCCO Mills conducted an exterior lighting reinspection. On this day I was able to observe the same lamp post as being out. That said the property had been lit but last night we also observed some structures in violation again they are 18, 12, and 9. I will also update SA & JMT with the findings. A citation has not been issued for last nights violation. JR

DATE: 10/05/2016 CCO: Joe Rodriguez RESULT: Notice of Violation COMMENTS: 10/5/16 New NOV issued from this complaint, SCCO DE and I went to the property and I issued the NOV to the staff member named Lucy, she said she would notify the owner immediately. JR

DATE: 10/10/2016 CCO: Joe Rodriguez RESULT: Reinspection

COMMENTS: 10/10/16 Myself and SCCO JT met with the owner and walked the property. I pointed out to him the street type lamp posts and he stated they were out when he purchased the property. He stated that since the lights were attached to the city street post they were not his responsibility. That said it was explained to him that since they are on his property it would be his responsibility to contact Oncore and set up service. He stated he would do so and also repair the building lights that were observed out. He did also ask how I can see them without coming inside the property and obtaining consent. He added and asked why didn't I just come inside and talk with them about it. JR

DATE: 10/31/2016 CCO: Joe Rodriguez

RESULT: Reinspection

COMMENTS: 10/31/16 I inspected the exterior lighting issues on 10/29/16, bdg 12 is out as well as the lamp posts pointed out to the property owner on 10/10/16. The pictures I took did not come out well and may be difficult to enforce with citations. I will refer with JMT & SA. JR

DATE: 11/16/2016 CCO: Joe Rodriguez

RESULT: Reinspection

COMMENTS: 11/16/16 Street lamps are still out, however pictures are not clear due to distance and light. I will discuss with JMT & SA. JR

DATE: 01/05/2017 CCO: Joe Rodriguez RESULT: Investigation/Research COMMENTS: 1/5/17 No change in lighting (Street lamps). JR

DATE: 02/27/2017 CCO: John Taylor RESULT: Reinspection COMMENTS: Working an after hours call this evening after dark.

DATE: 03/01/2017 CCO: Lesley Mills RESULT: Owner Abated COMMENTS: Per LM and JBT, no violations observed either evening, 2/27 nor 2/28/17

Additional Comments or Notes

Date: 03/15/2016 Made By: Joe Rodriguez

3/15/16 On 3/7/16 I received a phone call from the original light trespass complainant at 600 Matthews Dr. She thanked me for getting the property owners at 408 N Fielder Rd to comply with her request of adjusting the exterior lighting fixture at building #14. I did ask my FOM JMT if I should address the exterior lighting failures and he suggested we wait until the next exterior lighting inspection goes and address then if necessary. I conducted an early re-dawn inspection and observed multiple buildings with exterior lighting failures, and NOV will be issued to the property owner. JR

3/15/16 Myself & CCO Mills came to the property to post the NOV. The property owners were not on site, but I was able to speak with a staff member 'Yamie' and I explained the reason for my visit. She stated the owners would not return for at least another hour. I asked if I could leave the notice some where and she stated that she deliver the NOV to the owner personally. It should be noted that on the way out CCO Mills observed the office smoke detector was tampered with and covered with tape. She made mention of it to the manager Yamie, she stated that she would correct the smk detector. JR

END OF REPORT COMPLIANCE DATE: Mar 1 2017 8:57AM



Address: 408 N FIELDER ROAD SUITE Q272

Violation: Insect / Rodent Infestation Date Reported: Tuesday May 24, 2016

Assigned CCO: David Engel Proactive? No Code Ranger? Print Date: Thursday December 26, 2019 Complaint/Concern Number: 16-984804-CODE

Police PRA: 133 Police Beat: 330 Council District: 1 Mapsco Page: 82F

Concern Description

reports bedbug infestation. She states that the apt complex says that they can not treat because of previous chemical put down. Arlington Villages Apts. apt. #272

Code Compliance Officer Inspection Data

DATE: 05/25/2016 CCO: David Engel

RESULT: Notice of Violation

COMMENTS: called compl no answer no answer machine. staffed with sa. Per sa, Im and I went to the compls apt without stopping by the office first. we made contact with the compl who state they have bed bugs. compl went on to state that she was told by apt staff that the apt could not be treated because the compl put down diatomaceous earth around the base boards. compl stated her and her husband would remove the earth. went to office to issue nov. office staff was in court. spoke with maint who stated the pest control company told the office staff about the earth. Im and I departed the complex

DATE: 05/24/2016 CCO: Uniqua D. Hall RESULT: Call Received COMMENTS:

DATE: 06/28/2016 CCO: David EngelRESULT: Owner AbatedCOMMENTS: no further contact with compl. owner provided documentation n from pest control company

Additional Comments or Notes

END OF REPORT COMPLIANCE DATE: Jun 28 2016 8:14AM



Address: 408 N FIELDER ROAD SUITE N210

Violation: Unclean Premises Date Reported: Tuesday June 7, 2016

Assigned CCO: David Engel Proactive? No Code Ranger? No Print Date: Thursday December 26, 2019 Complaint/Concern Number: 16-993615-CODE

Police PRA: 133 Police Beat: 330 Council District: 1 Mapsco Page: 82F

Concern Description

RECEIVED CALL FROM OWNER ABOUT TOYS AND ITEMS BLOCKING THE UPSTAIRS ENTRANCE.

Code Compliance Officer Inspection Data

DATE: 06/07/2016 CCO: Lesley Mills RESULT: Notice of Violation COMMENTS: HANDWRITTEN NOV POSTED ON DOOR AREA

DATE: 06/07/2016 CCO: Lesley Mills RESULT: Call Received COMMENTS:

DATE: 06/13/2016 CCO: Lesley Mills RESULT: Owner Abated COMMENTS: SPOKE TO RESIDENT AT 9:30AM AND SHE REMOVED THE MAJORITY OF THE ITEMS AND A PLANT WAS LEFT WHICH I WASN'T TOO CONCERNED ABOUT, SO I WILL BE CLOSING OUT THIS COMPLAINT

Additional Comments or Notes

END OF REPORT COMPLIANCE DATE: Jun 13 2016 9:32AM



Address: 408 N FIELDER ROAD BLDG 09

Violation: Hazardous Mechanical Equipment Date Reported: Wednesday October 19, 2016

Assigned CCO: David Engel Proactive? No Code Ranger? Print Date: Thursday December 26, 2019 Complaint/Concern Number: 16-1082700-CODE

Police PRA: 133 Police Beat: 330 Council District: 1 Mapsco Page: 82F

Concern Description

reported to landlord a/c out 3 weeks ago and still not fixed. she put this writing

Code Compliance Officer Inspection Data

DATE: 10/19/2016 CCO: David Engel

RESULT: Notice of Violation

COMMENTS: met with residents. apt was cool when we were there. window unit installed as an interim. res stated window unit freezes up. did not when we were there but will mention it.

DATE: 10/25/2016 CCO: David Engel RESULT: Owner Abated COMMENTS: spoke to res who stated a/c resolved

Additional Comments or Notes

END OF REPORT COMPLIANCE DATE: Oct 25 2016 3:24PM



Address: 408 N FIELDER ROAD SUITE L175

Violation: No Air Conditioning Date Reported: Wednesday September 20, 2017

Assigned CCO: Laura King Proactive? No Code Ranger? Print Date: Thursday December 26, 2019 Complaint/Concern Number: 17-313872-CODE

Police PRA: 133 Police Beat: 330 Council District: 1 Mapsco Page: 82F

Concern Description

VM - The Arlington Village Apartments

resident has been without a/c since 9/15. She was told someone would come on Monday but they did not come to the home. This is apt #175, and the second seco

Code Compliance Officer Inspection Data

DATE: 09/20/2017 CCO: Victor Alfaro

RESULT: Notice of Violation

COMMENTS: Property has supplied apartment with window unit but it does not cool the entire unit. Outside 95 outside according to google and bedroom was 82 and living room was 79 according to infrared thermometer.

DATE: 09/20/2017 CCO: Lometa Jones RESULT: Call Received COMMENTS:

DATE: 09/22/2017 CCO: John Taylor RESULT: Issue Civil Citation

COMMENTS: Met with maintenance staff who admitted the existing system was still down due to ordered part has still not arrived. System has been down since last Friday. Victor's NOV allowed until yesterday to have corrected. Staff has provided temporary relief by providing two window units, one in the living room and one in the bedroom. I've informed Mngr that this citation will be issued to the owner of record. I will follow up on Monday for my second visit to verify the unit is in compliance.

DATE: 09/26/2017 CCO: John Taylor RESULT: Owner Abated COMMENTS: The tenant confirmed that all repairs were completed.

Additional Comments or Notes

Date: 09/20/2017 Made By: Victor Alfaro

Management was not onsite at the time we arrived we conducted the inspection with the tenant. After we finished the management returned and issued the management the notice. The management stated that the part was coming but wouldn't be her till Friday. I informed her that the unit need to be cooled down to the correct temp. She stated the which one the bedroom or living I informed her the entire unit need to be cooled to the correct temp.

END OF REPORT COMPLIANCE DATE: Sep 26 2017 10:31AM



Address: 408 N FIELDER ROAD BLDG 01

Violation: No Heat Date Reported: Thursday December 28, 2017

Assigned CCO: Laura King Proactive? No Code Ranger? Print Date: Thursday December 26, 2019 Complaint/Concern Number: 17-377823-CODE

Police PRA: 133 Police Beat: 330 Council District: 1 Mapsco Page: 82F

Concern Description

APT# 74

No Heater and they told her it will not be fixed until after the New Year, Tuesday or Thursday.

Code Compliance Officer Inspection Data

DATE: 12/28/2017 CCO: Victor Alfaro

RESULT: Notice of Violation

COMMENTS: Management confirmed that the unit did not fuction and A/C heating company was onsite. The manager stated she did not know when the unit would be repaired. Issuing notice of violation to inform the management on the time frame for repairs

DATE: 12/28/2017 CCO: Sylvia Martinez RESULT: Call Received COMMENTS:

DATE: 12/29/2017 CCO: Victor Alfaro RESULT: Owner Abated COMMENTS: Spoke to tenant stated issues resolved

Additional Comments or Notes

END OF REPORT COMPLIANCE DATE: Dec 29 2017 12:20PM



Address: 408 N FIELDER ROAD SUITE C24

Violation: No Heat Date Reported: Wednesday January 10, 2018

Assigned CCO: Laura King Proactive? No Code Ranger? Print Date: Thursday December 26, 2019 Complaint/Concern Number: 18-105492-CODE

Police PRA: 133 Police Beat: 330 Council District: 1 Mapsco Page: 82F

Concern Description

Arlington Village Apartments

, is reporting no heat to Unit 24. He has spoken with management several times since

November and still no repairs have been made.

Code Compliance Officer Inspection Data

DATE: 01/10/2018 CCO: Lynn TrotterRESULT: Notice of ViolationCOMMENTS: met with tenant heat is not working dropped off nov to manager

DATE: 01/10/2018 CCO: Lometa Jones RESULT: Call Received COMMENTS:

DATE: 01/11/2018 CCO: Lynn Trotter RESULT: Reinspection COMMENTS: spoke to tenant he said they are still working on it and have provided temporary heater

Laura and David E spoke to manager she said the maintenance was finishing up now and it has been repaired

DATE: 01/17/2018 CCO: Lynn Trotter RESULT: Owner Abated COMMENTS: did not hear back from tenant repairs were being made last Friday tenant was going to call me if not done

Additional Comments or Notes

END OF REPORT

Page **1** of **2**

COMPLIANCE DATE: Jan 17 2018 8:12AM



Address: 408 N FIELDER ROAD SUITE M181

Violation: Raw Sewage - Exterior Date Reported: Tuesday June 19, 2018

Assigned CCO: Kyle Jones Proactive? No Code Ranger? Print Date: Thursday December 26, 2019 Complaint/Concern Number: 18-090893-CODE

Police PRA: 133 Police Beat: 330 Council District: 1 Mapsco Page: 82F

Concern Description

anon reporting that the apartment complex: Arlington Village, 408 N fielder Rd, is pumping raw sewage from one of the buildings out into the parking lot. COMP advises that they do that from time to time and req city come out ASAP so that they can finally see it first hand. They have been doing this since 7AM. You can see it when you pull into the apartment complex: north side of the front parking lot by the office.

Code Compliance Officer Inspection Data

DATE: 06/19/2018 CCO: Kyle Jones

RESULT: Notice of Violation

COMMENTS: From the parking lot open to the general public CCO Trotter and I viewed raw sewage and the lid off of a clean out on the East side of building #20.

DATE: 06/20/2018 CCO: Kyle Jones

RESULT: Owner Abated

COMMENTS: From the public street ROW and from the parking lot open to the general public I no longer viewed the violation.

Additional Comments or Notes

Date: 06/19/2018 Made By: Kyle Jones

CCO Trotter and I handed the NOV along with the Sewer Overflow Information to a lady that answered the door of the office that had a note on it stating that the office is closed today. She stated that she knew of the situation and will have it cleaned up. I also called Alex Edwards to inform him of the raw sewage that is hitting the street per JMT request.

END OF REPORT



Address: 408 N FIELDER ROAD BLDG 01

Violation: Raw Sewage - Exterior Date Reported: Wednesday July 25, 2018

Assigned CCO: Kyle Jones Proactive? No Code Ranger? Print Date: Thursday December 26, 2019 Complaint/Concern Number: 18-113914-CODE

Police PRA: 133 Police Beat: 330 Council District: 1 Mapsco Page: 82F

Concern Description

The Arlington Village Apartments

caller is reporting sewage that is going straight to the street from the apartment buildings.

Code Compliance Officer Inspection Data

DATE: 07/25/2018 CCO: Kyle Jones

RESULT: Notice of Violation

COMMENTS: From the public street ROW and the parking lot open to the general public. CCO Trotter and I observed a clean out with sewage water coming out of it at the time of inspection.

DATE: 07/30/2018 CCO: Kyle Jones RESULT: Owner Abated COMMENTS: violation corrected

Additional Comments or Notes

Date: 07/26/2018 Made By: Kyle Jones

CCO Alfaro and I went to the property and observed toliet paper on the ground near the cleanout. The area did not apear to be sanitary. I will discuss what action needs to be taken with FOM Triplett

END OF REPORT COMPLIANCE DATE: Jul 30, 2018



Address: 408 N FIELDER ROAD BLDG 01

Violation: Insect / Rodent Infestation Date Reported: Monday August 27, 2018

Assigned CCO: Kyle Jones Proactive? No Code Ranger? Print Date: Thursday December 26, 2019 Complaint/Concern Number: 18-132012-CODE

Police PRA: 133 Police Beat: 330 Council District: 1 Mapsco Page: 82F

Concern Description

(would like to be contacted)

Comp said there is a big roach infestation in this complex. Landlord is aware of the situation but have not rectified it

Apt 43

Code Compliance Officer Inspection Data

DATE: 08/27/2018 CCO: Kyle Jones

RESULT: Investigation/Research

COMMENTS: I spoke to the resident at the property who stated her name was **set and the stated** I stated that myself and another CCO will come to inspect the unit at 1:00PM tomorrow.

DATE: 08/28/2018 CCO: Kyle Jones

RESULT: Notice of Violation

COMMENTS: With written consent from the tenant at the unit **COMMENTS** CCO Trotter and I viewed a roach infestation inside the unit. NOV was posted to the front door of the office at the property. CCO Trotter and I spoke with management before going to the unit with the violation. When we returned to issue the NOV the office was locked. After knocking and no answer the NOV was posted on the door.

DATE: 09/21/2018 CCO: Kyle Jones RESULT: Owner Abated COMMENTS: I have not received any contact from the complainant regarding this violation and the property has provided proof of having the apartment treated attached. I will close the complaint

Additional Comments or Notes

Date: 08/29/2018 Made By: Kyle Jones

I received a call from **Construction** who is the Property Manager at 408 N. Fielder Rd who stated that she never received a call from the tenant for any treatment for pest control however due to the property receiving the NOV she went ahead and scheduled for the treatment for today. I have attached the invoice from today into the attachment folder in the complaint.

END OF REPORT COMPLIANCE DATE: Sep 21, 2018



Address: 408 N FIELDER ROAD SUITE O235

Violation: Insect / Rodent Infestation Date Reported: Friday February 1, 2019

Assigned CCO: Kyle Jones Proactive? No Code Ranger? Print Date: Monday May 11, 2020 Complaint/Concern Number: 19-014593-CODE

Police PRA: 133 Police Beat: 330 Council District: 1 Mapsco Page: 82F

Concern Description

rodent infestation and rotted wood around windows. Comp states

that they have talked to office management more than a dozens times and nothing has been done.

Code Compliance Officer Inspection Data

DATE: 02/04/2019 CCO: Kyle Jones

RESULT: Monitor

COMMENTS: I spoke to a

who stated that there is an infestation inside

the unit. however he stated that management has sprayed inside the unit just 2 weeks ago, his compliant is that they haven't sprayed enough to fix the infestation. I made an appointment to inspect the unit tomorrow 2-5-2018 at 10:30AM

DATE: 02/05/2019 CCO: Kyle Jones

RESULT: Notice of Violation

COMMENTS: With written consent from **COMMENTS**: Who is the resident at the property. CCO Trotter, CCO Pizaro and I inspected the unit. The unit has what appears to be an Insect infestation based off the amount of roaches and droppings seen. Also while inside the unit it was observed that no smoke detectors were inside the unit. After talking with management she stated that the unit would be sprayed tomorrow and over the next couple of weeks as well, Along with installing smoke detectors. I am emailing this NOV to Nadia Miranda (scmanager@apartmentdfw.com) who is the property manager.

DATE: 03/14/2019 CCO: Kyle Jones RESULT: Owner Abated COMMENTS: Have not received any contact from complainant.

Additional Comments or Notes

END OF REPORT

Page 1 of 2

COMPLIANCE DATE: Mar 14, 2019



Address: 408 N FIELDER ROAD BLDG 01

Violation: Raw Sewage - Exterior Date Reported: Monday February 11, 2019

Assigned CCO: Kyle Jones Proactive? No Code Ranger? Print Date: Monday May 11, 2020 Complaint/Concern Number: 19-018598-CODE

Police PRA: 133 Police Beat: 330 Council District: 1 Mapsco Page: 82F

Concern Description

KJ on 2-11-2019 I was told by North Code Supervisor Ann Ebert that there had been a Raw Sewage violation at 408 N Fielder for The Village Apartment complex over the weekend.

Code Compliance Officer Inspection Data

DATE: 02/11/2019 CCO: Kyle Jones RESULT: Monitor

COMMENTS: After speaking with Code Supervisor Ebert, as instructed I took Senior CCO Mills with me to inspect the property. When arriving at the property there was no violation seen on the property however it was observed that maintenance was sanitizing the affected area. Senior CCO Mills and I spoke with Dylan Tissue with Environmental about the situation at the property. He stated that he was called out to the property over the weekend and was at the property Saturday night and could not make any contact with anyone at the property. He then stated that he spoke with Craig Goldman who is the property owner on Sunday. Mr. Goldman stated to him that a plumber has fixed the issue and should no longer be a problem. Senior CCO Mills and I went to the office to speak to Mr. Goldman however he was not at the property at this time. Instead I spoke with a property manager that was in the office. I explained to her how there will be no more notices for this violation, the property has received plenty of them so from now on we will be fully enforcing the violation and will issue a citation for this violation without any warning should it happen again.

Per management I have been asked to set this to monitor and periodically go by the property to check for this violation over the next week.

DATE: 02/11/2019 CCO: Doug Stewart

RESULT: Issue Citation

COMMENTS: Sewage overflow at apartment complex. Overflow coming from clean out in ground next to building #20. No response from Owner or management. Previous notice has been issued for same violation and same location on property. Cite #000660605-01 issued and mailed to owner, Craig Goldman for unclean premises-raw sewage.

DATE: 02/14/2019 CCO: Kyle Jones

RESULT: Monitor

COMMENTS: After arriving at the property I searched for a raw sewage spill around building 20 which is where previous spills have been. I called the complainant and and left a voicemail requesting a call back. Shortly after the returned my call and stated that the spill this morning was at the office building (North side of building 11) around 9:00AM. CCO Pizarro and I then spoke to the manager at the property who stated that they did have a raw sewage spill this morning but have since had it cleaned and repaired by a plumbing company. She made me a copy of the invoice from this morning to show that they have in fact have had a plumbing company out to inspect the issue. CCO Pizarro and I also inspected the area of where the spill was. The area looked to be cleaned and did not smell. The photos I took of the area are attached above.

DATE: 02/17/2019 CCO: Shannon Greene

RESULT: Monitor

COMMENTS: Property was in violation when viewed from the public street ROW. Large amount of raw sewage on the back of the building on the West side and in front of the building on the East Side as well. Pictures were taken and environmental was contacted. When attempting to contact owner and apt MGMT, they could not be reached. Environmental Alexandria Edwards stated that she would investigate further. Photos taken at time of inspection.

DATE: 02/19/2019 CCO: Kyle JonesRESULT: MonitorCOMMENTS: I did not view any violations on the property at the time of inspection will set to monitor.

DATE: 02/20/2019 CCO: Shannon GreeneRESULT: Issue CitationCOMMENTS: After staffing with FOM JMT. Cite will be issued to property owner from inspection on 2/17/19

DATE: 02/25/2019 CCO: Kyle Jones

RESULT: Issue Citation

COMMENTS: Based off an affidavit which was filled out by Environmental Officer Alexandria Edwards I will issue Criminal Citation 000803706-1 to the TAD listed property owner Craig Goldman

DATE: 04/04/2019 CCO: Kyle JonesRESULT: Owner AbatedCOMMENTS: No Raw Sewage seen or received complaints since February. Will close the complaint

Additional Comments or Notes

END OF REPORT

COMPLIANCE DATE: Apr 04, 2019



Address: 408 N FIELDER ROAD BLDG 06

Violation: Insect / Rodent Infestation Date Reported: Thursday April 25, 2019

Assigned CCO: Kyle Jones Proactive? No Code Ranger? Print Date: Monday May 11, 2020 Complaint/Concern Number: 19-056896-CODE

Police PRA: 133 Police Beat: 330 Council District: 1 Mapsco Page: 82F

Concern Description

- The Village Apts, #6

Comp rpts roach infestation inside her apt. States they may have laid their eggs inside her t.v.

Roaches are in her kitchen, bathrooms, bedroom closets, beds, crib etc..

Reported to mngt, they've sent someone out to spray but that doesn't seem to be helping. Has sent them emails as well.

Code Compliance Officer Inspection Data

DATE: 05/02/2019 CCO: Kyle Jones RESULT: Notice of Violation COMMENTS: I handed a NOV to the property manager at the property.

DATE: 05/22/2019 CCO: Kyle Jones RESULT: Owner Abated COMMENTS: Have not received any contact from the complainant. I will close the complaint

Additional Comments or Notes

END OF REPORT COMPLIANCE DATE: May 22, 2019



Address: 408 N FIELDER ROAD SUITE K154

Violation: Faulty Weather Protection Date Reported: Friday May 31, 2019

Assigned CCO: Kyle Jones Proactive? No Code Ranger? Print Date: Monday May 11, 2020 Complaint/Concern Number: 19-074503-CODE

Police PRA: 133 Police Beat: 330 Council District: 1 Mapsco Page: 82F

Concern Description

who stated he has water leaking through his ceiling and the

ceiling has damage as well

I received a call from

Code Compliance Officer Inspection Data	Code	Comp	liance	Officer	Inspection	Data
---	------	------	--------	---------	------------	------

DATE: 05/31/2019 CCO: Kyle Jones

RESULT: Notice of Violation

COMMENTS: With written consent from CCO Trotter and I inspected the property. Upon

inspection damage to the ceiling was found along with a bucket of water underneath where the damage to the ceiling is

I emailed a NOV to the property manager at manager@arlingtonvillageapartments.com

DATE: 06/11/2019 CCO: Kyle Jones RESULT: Monitor COMMENTS: I attempted to call the complainant **Complete Complete Comple**

DATE: 06/13/2019 CCO: Kyle Jones RESULT: Owner Abated COMMENTS: No contact has been received from complainant. I will close out this case.

Additional Comments or Notes

END OF REPORT COMPLIANCE DATE: Jun 13, 2019



Address: 408 N FIELDER ROAD BLDG 01

Violation: No Heat Date Reported: Thursday December 28, 2017

Assigned CCO: Laura King Proactive? No Code Ranger? Print Date: Thursday December 26, 2019 Complaint/Concern Number: 17-377823-CODE

Police PRA: 133 Police Beat: 330 Council District: 1 Mapsco Page: 82F

Concern Description

APT# 74

No Heater and they told her it will not be fixed until after the New Year, Tuesday or Thursday.

Code Compliance Officer Inspection Data

DATE: 12/28/2017 CCO: Victor Alfaro

RESULT: Notice of Violation

COMMENTS: Management confirmed that the unit did not fuction and A/C heating company was onsite. The manager stated she did not know when the unit would be repaired. Issuing notice of violation to inform the management on the time frame for repairs

DATE: 12/28/2017 CCO: Sylvia Martinez RESULT: Call Received COMMENTS:

DATE: 12/29/2017 CCO: Victor Alfaro RESULT: Owner Abated COMMENTS: Spoke to tenant stated issues resolved

Additional Comments or Notes

END OF REPORT COMPLIANCE DATE: Dec 29 2017 12:20PM



Address: 408 N FIELDER ROAD BLDG 02

Violation: Insect / Rodent Infestation Date Reported: Wednesday June 26, 2019

Assigned CCO: Kyle Jones Proactive? No Code Ranger? Print Date: Monday May 11, 2020 Complaint/Concern Number: 19-087926-CODE

Police PRA: 133 Police Beat: 330 Council District: 1 Mapsco Page: 82F

Concern Description

reports her apartment is bed bug infestation. apt# 51

Code Compliance Officer Inspection Data

DATE: 06/26/2019 CCO: Kyle Jones

RESULT: Notice of Violation

COMMENTS: I emailed a NOV to the property manager at the property and also mailed a NOV to the TAD listed property owner.

DATE: 07/01/2019 CCO: Kyle Jones

RESULT: Owner Abated

COMMENTS: I received an email from the manager of the property Cynthia Poblano

(manager@arlingtonvillageapartments.com) who stated that they had the apartment inspected and also provided me with an invoice of the Certified Professional who came and inspected the unit (See Attachments). The invoice stated that no bed bugs were found and no trace of bed bugs were seen at the time of inspection.

I attempted to call the complainant **example and the mailbox** was full so no message was left. I will close out the complaint

Additional Comments or Notes

END OF REPORT COMPLIANCE DATE: Jul 01, 2019



Address: 408 N FIELDER ROAD BLDG 01

Violation: Other - Non Life Safety Date Reported: Friday July 19, 2019

Assigned CCO: Kyle Jones Proactive? No Code Ranger? Print Date: Monday May 11, 2020 Complaint/Concern Number: 19-097412-CODE

Police PRA: 133 Police Beat: 330 Council District: 1 Mapsco Page: 82F

Concern Description

No representation for FY 19 Multi Family Training

Code Compliance Officer Inspection Data

DATE: 07/19/2019 CCO: David Engel

RESULT: Notice of Violation

COMMENTS: Mailed NOV for No representation for FY 19 Multi Family Training to property and owner

DATE: 08/01/2019 CCO: Kyle Jones

RESULT: Owner Abated

COMMENTS: Closing complaint due to NOV being sent and the next available MF Workshop will not be until next year.

Additional Comments or Notes

END OF REPORT COMPLIANCE DATE: Aug 01, 2019



Address: 408 N FIELDER ROAD BLDG 01

Violation: No Heat Date Reported: Tuesday November 5, 2019

Assigned CCO: Kyle Jones Proactive? No Code Ranger? Print Date: Monday May 11, 2020 Complaint/Concern Number: 19-141126-CODE

Police PRA: 133 Police Beat: 330 Council District: 1 Mapsco Page: 82F

Concern Description

States she does not have air or heat in the apartment for a while #254. Also has a leak in the bathroom and can not take bath been this way for three weeks now.

Code Compliance Officer Inspection Data

DATE: 11/06/2019 CCO: Kyle Jones

RESULT: Notice of Violation

COMMENTS: With written consent from the tenant **CCO** Trotter, the property owner Craig Goldman, and I inspected the unit at the property. upon the inspection it was observed that the AC/Heater was not working at all at the time of inspection. Mr. Goldman stated that he spoke with his office staff and they have the part to have the AC/Heater fixed. I will still email an NOV to the property management.

DATE: 11/21/2019 CCO: Kyle Jones RESULT: Owner Abated COMMENTS: I received an email from the complainant who stated that the violation has been corrected. (See Attachments)

DATE: 11/18/2019 CCO: Kyle Jones RESULT: Monitor

COMMENTS: I received a phone call and an email from the complainant who stated that she is still without heat inside of her unit at the property. I emailed the manager and the property owner Craig Goldman in regards to this complaint. Email is in the attachment folder.

Additional Comments or Notes

END OF REPORT COMPLIANCE DATE: Nov 21, 2019

Date 09/25/2014

Type Pre-REAC

Score 71

Area	Pts. Lost (Gross)	Poss. Points	Pts. Lost (Cap)	Score	Violations
Site	4.22	15	4.22	10.78	12
Exterior	0	15	0	15	3
Systems	0	20	0	20	0
Common	13.74	15	13.74	1.26	16
*Units	5.29	35	11.23	23.77	34
Total	23.24	100	29.19	70.81	65

Units Area score is projected for the REAC sample size based on the average unit score

Location	Item	Deficiency	Notes	Pic	Sev	HS	LT	Pts	Date	Fixe
⁻ ence/Gate	Entire Location	General Comment	Graffiti next to building one needs to be	1			N/A	0	Sep 25 2014	
Grounds	Vegetation	General Comment	removed Broken branches	2			N/A	D	2:28PM Sep 25	
			located in between						2014	
			building 5 and 6 need to be removed						2:25PM	
Grounds	Vegetation	General Comment	Broken branches next to building one needs to be	3			N/A	0	Sep 25 2014	
Health & Safety	Health & Safety	General Comment	removed Cable box by building	4			N/A	0	2:29PM Sep 25	
iouis, a outory	ficanti a calog		one needs to be repaired	Ŧ			N/A	U	2014 2:27PM	
icenses and Permits	Multifamily License	CERTIFICATION:	Return multi-family				N/A	0.	Sep 25	
	,,	Missing/Expired/or Not Displayed	application within 30 days of 9-25-14				1947	v	2014 3:45PM	
Refuse Disposal	Refuse Disposal Area	General Comment	Graffiti in dumpster	5			N/A	0	Sep 25	
			enclosure needs to be						2014	
			removed						2:19PM	
Roads/Parking/Curbs	Roads/Parking/Curbs	STRIPING: Fire Lanes not	Parking lot needs to be	<u>6</u>			N/A	0	Sep 25	
		properly marked	stripped						2014	
Roads/Parking/Curbs	Poode/Porking/Curbs	CTDIDNO: Foded on Marian						-	2:14PM	
coads/Parking/Curbs	Roads/Parking/Curbs	STRIPING: Faded or Missing	Missing cover needs to				N/A	0	Sep 25	
		Parking Lot Striping	be replace						2014 2:13PM	
toads/Parking/Curbs	Roads/Parking/Curbs	STRIPING: Faded or Missing	Parking lot needs to be				N/A	0	Sep 25	
	rietter analigi oalbo	Parking Lot Striping	stripped				19/7	U	2014	
		······································							2:14PM	
loads/Parking/Curbs	Roads/Parking/Curbs	General Comment	Parking not stripped	z			N/A	0	Sep 25	
									2014	
									2:16PM	
loads/Parking/Curbs	Roads/Parking/Curbs	General Comment	Weeds need to be	<u>8</u>			N/A	0	Sep 25	
			removed from the						2014	
) de (De drie e (Cruche	Deeds (Deddees (Out -		parking lot	-					2:17PM	
Roads/Parking/Curbs	Roads/Parking/Curbs	TRIPPING: Any obstruction or defect in a surface that causes	Missing cover needs to	<u>9</u>	L3	х	NLT	4.22	Sep 25	
		tripping	be replace						2014	
		Exterio	r						2:13PM	
08 N FIELDER RO	AD									
Location	ltem	Deficiency	Notes	Pic	Sev	HS	LT	Pts	Date	Fixed
ntire Building	Entire Location	General Comment		10			N/A	0	Sep 25	
									2014	
									2:22PM	
ntire Building	Entire Location	General Comment	Repair and/or replace	11			N/A	0	Sep 25	
			cable box door						2014	
ealth & Safety	Health & Safety	OTHER: Herende not otherwise	Minning anyon and the	40				~	3:39PM	
ealur & Salety	Health & Salety	OTHER: Hazards not otherwise included in inspection code - see	Missing cover needs to be replace	12	L3	x	NLT	0	Sep 25	
		notes for detail	De l'éplace						2014 2:12PM	
		Common A	Area				il all			
08 N FIELDER RO	AD									
Location	Item	Deficiency	Notes	Pic	Sev	HS	LT	Pts	Date	Fixed
ealth & Safety	Health & Safety	General Comment	Build ten has appliances left unsecured	<u>13</u>			N/A	0	Sep 25 2014	
									2:43PM	
ealth & Safety	Health & Safety	General Comment		14			N/A	0	Sep 25	

									2014
Health & Safety	Health & Safety	OTHER: Hazards not otherwise included in inspection code - see notes for detail	Vehicle on the jackstand by build 10	<u>15</u>	L3	x	NLT	0	2:43PM Sep 25 2014 2:41PM
Laundry Room	Dryer Vent	SHARP EDGES: Any defect that could pose a cutting risk	Remove, repair, and/or replace damaged vent	<u>16</u>	L3	х	NLT	3.15	Sep 25 2014 3:22PM
Laundry Room	Floor - Hard	TRIPPING: Any obstruction or defect in a surface that causes tripping	Ensure tripping hazard outside of laundry room/storage room is removed.	17	L3	х	NLT	D	Sep 25 2014 3:24PM
Laundry Room	Smoke Detector	General Comment	Remove non-used smoke detector housing or replace with second smoke detector	<u>18</u>			N/A	D	Sep 25 2014 3:18PM
Laundry Room	Smoke Detector	General Comment	That is in laundry room to building 17				N/A	0	Sep 25 2014 3:18PM
Laundry Room	Washer/Dryer	General Comment	Trash behind washer and dryer	19			N/A	0	Sep 25 2014 2:18PM
Laundry Room	Window Seals/Sills	General Comment	Replace broken window	20			N/A	0	Sep 25 2014 3:19PM
Laundry Room	Windows	PANES: Cracked or broken window panes		21	L3	×	NLT	3.15	Sep 25 2014 2:20PM
Office	Door - Interior	FRAME: Damage to frame/lintel/threshold/interior door jamb	Replace weather stripping	<u>22</u>	L2		N/A	0.44	Sep 25 2014 2:01PM
Office	Entire Location	General Comment	CO is not posted on property				N/A	C	Sep 25 2014 1:58PM
Office	Smoke Detector	General Comment	Painted smoke detector	<u>23</u>			N/A	0	Sep 25 2014 1:57PM
Office	Smoke Detector	FIRE SAFETY: Smoke detector inoperable/missing		24	L3	х	LT	0	Sep 25 2014 2:00PM
Storage Room	Electric Panel	EXPOSED WIRES: Cover is missing - exposed electrical connections		<u>25</u>	L3	x	LT	3.5	Sep 25 2014 3:20PM
Storage Room	Electric Panel	EXPOSED WIRES: Any loose/unsecured section of a panel cover		<u>26</u>	L3	x	LT	3.5	Sep 25 2014 3:20PM
		Unit							

408 N FIELDER ROAD UNIT:D34

Location	Item	Deficiency	Notes	Pic	Sev	HS	LT	Pts	Date	Fixed
Entry Door	Door - Entry/Fire/Bath	General Comment	Gaps in the door frame needs to be filled	27			N/A	0	Sep 25 2014 2:07PM	
Kitchen	Outlets/Switches	General Comment	Painted wall socket kitchen	<u>28</u>			N/A	0	Sep 25 2014 2:08PM	
Living Room	Outlets/Switches	General Comment	Label bbox	<u>29</u>			N/A	C	Sep 25 2014 2:14PM	
Living Room	Smoke Detector	FIRE SAFETY: Smoke detector inoperable/missing	Missing in hallway	<u>30</u>	L3	х	LT	0	Sep 25 2014 2:12PM	

Unit

408 N FIELDER R	OAD UNIT:D35							
Location	Item	Deficiency	Notes	Pic Sev HS	LT	Pts	Date	Fixed
Entry Doo r	Door - Entry/Fire/Bath	General Comment	Separation between boards on frame.	<u>31</u>	N/A	0	Sep 25 2014 2:09PM	


Unit

Location	ltem	Deficiency	Notes	Pic	Sev	HS	LT	Pts	Date	Fixed
Bathroom 1	Toilet	General Comment	Running toilet				N/A	0	Sep 25 2014 2:31PM	
Entire Unit	Housekeeping	HOUSEKEEPING: Excessive Clutter or Disorganized Area		32			N/A	0	Sep 25 2014 2:32PM	
Living Room	Walls	General Comment		<u>33</u>			N/A	0	Sep 25 2014 2:28PM	
Local Systems	Electric Panel	LABELS: Breakers or circuits in panel not labeled	Label all breaker boxes throughout the property	<u>34</u>			N/A	0	Sep 25 2014 2:30PM	

408 N FIELDER R	OAD UNIT: F65									
Location	Item	Deficiency	Notes	Pic	Sev	HS	LT	Pts	Date	Fixe
Kitchen	GFCI	GFCI: Outlet does not test or is not operating		35	L3	x	NLT	0.7	Sep 25 2014	
Kitchen	Outlets/Switches	COVERS: Outlet/switch has broken/losse cover plate - no		<u>36</u>	L1		N/A	0.03	2014	
Kitchen	Stove/Range	exposed wires MISSING: Range/stove is missing where required		<u>37</u>	L3		N/A	0.47	2014	
		Unit			No. 1		10.00		2:44PM	
408 N FIELDER R	OAD LINIT G83	Onit				49.516.5			병행님 그 김상	
	1123	Deficiency	Materia		~					
Location Bathroom 1	Item Ceiling	Deficiency SURFACE:	Notes	9ic 38	Sev L3	HS	LT N/A	Pts 0.17	Date Sep 25	Fixe
	-	Bulging/buckling/sagging or problem with alignment			LJ				2014 2:37PM	
Living Room	Smoke Detector	General Comment	Replace painted smoke detector	<u>39</u>			N/A	C	Sep 25 2014 2:37PM	
Living Room	Smoke Detector	FIRE SAFETY: Smoke detector inoperable/missing		<u>40</u>	L3	x	LT	0	Sep 25 2014 2:38PM	
المحمد والأقاد والمراجع		Unit							2.30PM	
408 N FIELDER RO	DAD UNIT:H112									
Location	ltem	Deficiency	Notes	Pic	Sev	HS	LT	Pts	Date	Fixe
Entire Unit	Entire Location	General Comment	Window screen in unit 112 building 9 needs		Jev		N/A	0	Sep 25 2014	TiAt
		Unit	repair						2:40PM	
408 N FIELDER RO		UIII								
					_					
Location Bathroom 1	Item Cabinets/Vanity	Deficiency CABINETS: Medicine cabinet damaged	Notes Cabinets Do not shut property	Pic 41	Sev L1	HS	LT N/A	Pts 0.07	Date Sep 25 2014	Fixe
Kitchen	Sink	LEAK: A steady leak or drip in basin/sink/associated piping	p.op.o	<u>42</u>	L3	x	NLT	0.63	2:57PM Sep 25	
Living Room	Housekeeping	HOUSEKEEPING: Pet Waste or		<u>43</u>			N/A	o	2014 2:55PM Sep 25	
iving Room	Outlets/Switches	Other Pet Issues Present COVERS: Outlet/switch has		<u>44</u>	L3	x	LT	1.05	2014 2:57PM Sep 25	
iving Room	Smoke Detector	broken/missing cover plate - exposing wires FIRE SAFETY: Smoke detector		<u>45</u>	L3	x	LT	0	2014 2:58PM Sep 25	
		inoperable/missing							2014 2:57PM	
		Unit								
108 N FIELDER RO										
Location Bathroom 1	ltem Sink	Deficiency General Comment	Notes		Sev	HS	LT	Pts	Date	Fixe
			Sink has some discoloration	<u>46</u>			N/A	0	Sep 25 2014 3:04PM	
lathroom 1	Sink	SINK: Basin has cracks or discoloration in more than 50% of the area	Sink has some discoloration		L1		N/A	0.12	Sep 25 2014 3:04PM	
ledroom 1	Windows	LOCK: Inoperable/not locking - lock is broken and window is not secure	Broken window lock needs to be replace	47	L3	x	NLT	0.14	Sep 25 2014 3:05PM	
loset/Storage Room	Door - Closet	General Comment	Missing door	<u>48</u>			N/A	0	Sep 25 2014	
ocal Systems	Water Heater	General Comment	Replace hole in ceiling sheet rock	<u>49</u>			N/A	0	3:03PM Sep 25 2014	
ocal Systems	Water Heater	VALVE: Pressure relief valve missing or does not extend to	Replace hole in celling sheet rock	50	L3	x	NLT	0.7	3:08PM Sep 25 2014	
	Several instances	within 18in. of floor Unit	ما ومعروبانت						3:08PM	
08 N FIELDER RO	AD UNIT:M187	onn								
Location	ltem	Deficiency	Notos	Die	80.	Le		Dec	Dete	E 1-
ntire Unit	No Issues/Violations	General Comment	Notes Unit was recently remodeled	FIC	Sev		LT N/A	Pts 0	Date Sep 25 2014	Fixe
									3:16PM	

		panel not labeled							2014	
		Unit						ven)		
408 N FIELDER R	OAD UNIT:0225									
Location	ltem	Deficiency	Notes	Pic	Sev	HS	LT	Pts	Date	Fixed
Kitchen	Sink	General Comment	Sink basin drain rusted and corroded	<u>51</u>			N/A	0	Sep 25 2014 3:26PM	
Living Room	Windows	LOCK: Inoperable/not locking - lock is broken but window is secure	Repair broken lock	<u>52</u>	L1		N/A	0.04	Sep 25 2014 3:28PM	
Local Systems	Water Heater	VALVE: Pressure relief valve missing or does not extend to within 18in. of floor	TPR valve missing	<u>53</u>	L3	x	NLT	0.7	Sep 25 2014 3:25PM	
		Unit								
408 N FIELDER R	OAD UNIT:Q263									
Location	Item	Deficiency	Notes	Pic	Sev	HS	LT	Pts	Date	Fixed
Bathroom 1	Windows	General Comment	Cracked window	<u>54</u>			N/A	0	Sep 25 2014 3:35PM	
Bathroom 1	Windows	SHARP EDGES: Any defect that could pose a cutting risk	Repair and/or replace broken window	<u>55</u>	L3	x	NLT	0.47	Sep 25 2014 3:34PM	

Inspection Results: 408 N. Fielder Road - 09/25/2014






Inspection Results: 408 N. Fielder Road - 09/25/2014









<u>28</u>















31

<u>34</u>






Inspection Results: 408 N. Fielder Road - 09/25/2014



<u>37</u>



39










<u>42</u>



<u>43</u>







47




<u>48</u>

Inspection Results: 408 N. Fielder Road - 09/25/2014




<u>49</u>




51



<u>52</u>



<u>53</u>





 Date
 09/09/2015
 Type
 Pre-REAC
 Score
 86

Area	Pts. Lost (Gross)	Poss. Points	Pts. Lost (Cap)	Score	Violations
Site	0	15	0	15	5
Exterior	0	15	0	15	1
Systems	0	20	0	20	0
Common	0.79	15	0.79	14.21	5
*Units	23.63	35	12.75	22.25	130
Total	24.41	100	13.54	86.46	141

 $^{\star}\textsc{Units}$ Area score is projected for the REAC sample size based on the average unit score *

		Entire Si	ite							
Site										
Location	Item	Deficiency	Notes	Pic	Sev	HS	LT	Pts	Date	Fixed
Entire Area	Entire Site	CURB APPEAL: City sidewalk in poor repair	repair all trip hazards around entire property including cracks in the sidewalks				N/A	0	Sep 10 2015 9:13AM	
Entire Area	Entire Site	General Comment	spray entire property for roaches and ants				N/A	0	Sep 10 2015 9:44AM	
Grounds	Entire Location	General Comment	Remove all dog poop from around entire property. Place covers around the holes that are located in your courtyard areas. Replace and paint over all rotted wood throughout property especially under the stairwells, landings, etc. Replace all missing light fixtures and coroaded ones around the entire property. Repair all lights to where they go on and off at the appropriate time. Romove all outside storage from the top landings and around your entire property. Make sure all trash is picked up around entire property at all times.				N/A	0	Sep 10 2015 9:23AM	
Grounds	Vegetation	General Comment	Trim low hanging tree limbs and trim the limbs that are close to your building areas so they want mess up the trim and ur roof areas				N/A	0	Sep 10 2015 9:16AM	
Licenses and Permits	Multifamily License	General Comment	need completed multifamily packet license				N/A	0	Sep 10 2015 9:12AM	
		Exterio	r							
408 N FIELDER RC	DAD									
Location	ltem	Deficiency	Notes	Pic	Sev	HS	LT	Pts	Date	Fixed
Entire Building	Entire Location	General Comment	Replace all broken blinds throughout entire property				N/A	0	Sep 10 2015 11:48AM	

400 NUELEL DED DO										
408 N FIELDER RO Location	AD Item	Deficiency	Notes	Pic	Sev	HS	LT	Pts	Date	Fixed
Laundry Room	Accessories	General Comment	Repair Sheetrock in back of dryer areas In laundry closet to Sanford st and place fire extinguisher in laundry closet to division st				N/A	0	Sep 10 2015 10:35AM	
Laundry Room	Heat/AC Cover	General Comment	Remove old ac system from laundry area closet to division st				N/A	0	Sep 10 2015 11:52AM	
Laundry Room	Smoke Detector	FIRE SAFETY: Smoke detector inoperable/missing	In both laundry areas		L3	х	LT	0	Sep 10 2015 10:36AM	
Laundry Room	Windows	PANES: Cracked or broken window panes - no sharp edges	back laundry room		L1		N/A	0.79	Sep 10 2015 10:35AM	
Storage Room	Smoke Detector	FIRE SAFETY: Smoke detector inoperable/missing	In shop area and paint hole in ceiling area		L3	х	LT	0	Sep 10 2015 11:01AM	
		Unit								
408 N FIELDER RO Location	AD UNIT:B09	Deficiency	Notes	Dic	Sev	цс	ιт	Dte	Date	Fixed
Location	item	Denciency		FIC	Sev	пэ	L1	FIS	Date	FIXed
Entire Unit	Housekeeping	General Comment	Remove outside storage unit 9				N/A	0	Sep 10 2015 11:44AM	
		Unit								
408 N FIELDER RO Location	AD UNIT:B12	Deficiency	Notes	Die	Sev	це	н т	Pts	Date	Fixe
Kitchen	Dishwasher/Disposal	EXPOSED WIRES: Unsecured cover/wires/connections creating a	clamp in disposal in unit	FIC	L3	x	LT	1.05	Sep 10 2015 9:52AM	TINC
		hazard	212							
Local Systems	Electric Panel	LABELS: Breakers or circuits in	unit 212				N/A	0	Sep 10 2015	
Local Systems	Electric Panel	LABELS: Breakers or circuits in panel not labeled	unit 212				N/A	0	Sep 10 2015 9:52AM	
		LABELS: Breakers or circuits in	unit 212				N/A	0		
408 N FIELDER RO	AD UNIT:B15	LABELS: Breakers or circuits in panel not labeled Unit		Pic	Sev	HS		_	9:52AM	Fixe
408 N FIELDER RO Location		LABELS: Breakers or circuits in panel not labeled	unit 212 Notes Unit 215	Pic	Sev L3	HS X		_		Fixe
408 N FIELDER RO Location Bedroom 1	AD UNIT:B15 Item	LABELS: Breakers or circuits in panel not labeled Unit Deficiency FIRE SAFETY: Smoke detector	Notes	Pic			LT LT	Pts	9:52AM Date Sep 10 2015	Fixe
408 N FIELDER RO Location Bedroom 1 Bedroom 1	AD UNIT:B15 Item Smoke Detector	LABELS: Breakers or circuits in panel not labeled Unit Deficiency FIRE SAFETY: Smoke detector inoperable/missing EGRESS: Emergency fire exit blocked/unusable - blocked	Notes Unit 215 bedroom area in unit	Pic	L3	X	LТ LТ	Pts 0	9:52AM Date Sep 10 2015 9:48AM Sep 10 2015	Fixe
408 N FIELDER RO Location Bedroom 1 Bedroom 1 Entry Door	AD UNIT:B15 Item Smoke Detector Windows	LABELS: Breakers or circuits in panel not labeled Unit Deficiency FIRE SAFETY: Smoke detector inoperable/missing EGRESS: Emergency fire exit blocked/unusable - blocked egress SEALS: Deteriorated/Missing Seals/Caulking/Glazing	Notes Unit 215 bedroom area in unit 215	Pic	L3 L3	X	LT LT LT	Pts 0 1.05	9:52AM Date Sep 10 2015 9:48AM Sep 10 2015 9:50AM Sep 10 2015	Fixe
408 N FIELDER RO Location Bedroom 1 Bedroom 1 Entry Door Health & Safety	AD UNIT:B15 Item Smoke Detector Windows Door - Entry/Fire/Bath	LABELS: Breakers or circuits in panel not labeled Unit Deficiency FIRE SAFETY: Smoke detector inoperable/missing EGRESS: Emergency fire exit blocked/unusable - blocked egress SEALS: Deteriorated/Missing Seals/Caulking/Glazing Compound (Light Around Door) EXPOSED WIRES: Unsecured cover/wires/connections creating a	Notes Unit 215 bedroom area in unit 215 unit 215 cover on ac missing in	Pic	L3 L3 L3	x	LT LT N/A LT	Pts 0 1.05 0.08	9:52AM Date Sep 10 2015 9:48AM Sep 10 2015 9:50AM Sep 10 2015 9:47AM	Fixed
408 N FIELDER RO Location Bedroom 1 Bedroom 1 Entry Door Health & Safety Kitchen	AD UNIT:B15 Item Smoke Detector Windows Door - Entry/Fire/Bath Health & Safety	LABELS: Breakers or circuits in panel not labeled Unit Deficiency FIRE SAFETY: Smoke detector inoperable/missing EGRESS: Emergency fire exit blocked/unusable - blocked egress SEALS: Deteriorated/Missing Seals/Caulking/Glazing Compound (Light Around Door) EXPOSED WIRES: Unsecured cover/wires/connections creating a hazard EXPOSED WIRES: Unsecured cover/wires/connections creating a	Notes Notes Unit 215 bedroom area in unit 215 unit 215 cover on ac missing in unit 215 clamp missing	Pic	L3 L3 L3 L3	x x x	LT LT N/A LT	Pts 0 1.05 0.08 1.05	9:52AM Date Sep 10 2015 9:48AM Sep 10 2015 9:50AM Sep 10 2015 9:47AM Sep 10 2015 9:49AM	Fixed
408 N FIELDER RO Location Bedroom 1 Bedroom 1 Entry Door Health & Safety Kitchen	AD UNIT:B15 Item Smoke Detector Windows Door - Entry/Fire/Bath Health & Safety Dishwasher/Disposal	LABELS: Breakers or circuits in panel not labeled Unit Deficiency FIRE SAFETY: Smoke detector inoperable/missing EGRESS: Emergency fire exit blocked/unusable - blocked egress SEALS: Deteriorated/Missing Seals/Caulking/Glazing Compound (Light Around Door) EXPOSED WIRES: Unsecured cover/wires/connections creating a hazard EXPOSED WIRES: Unsecured cover/wires/connections creating a hazard COVERS: Outlet/switch has broken/loose cover plate - no	Notes Notes Unit 215 bedroom area in unit 215 unit 215 cover on ac missing in unit 215 clamp missing in disposal	Pic	L3 L3 L3 L3 L3	x x x	LT LT N/A LT	Pts 0 1.05 0.08 1.05 1.05	9:52AM Date Date Sep 10 2015 9:48AM Sep 10 2015 9:50AM Sep 10 2015 9:49AM Sep 10 2015 9:49AM Sep 10 2015	Fixe
408 N FIELDER RO Location Bedroom 1 Bedroom 1 Entry Door Health & Safety Kitchen Living Room 408 N FIELDER RO	AD UNIT:B15 Item Smoke Detector Windows Door - Entry/Fire/Bath Health & Safety Dishwasher/Disposal Outlets/Switches	LABELS: Breakers or circuits in panel not labeled Unit Deficiency FIRE SAFETY: Smoke detector inoperable/missing EGRESS: Emergency fire exit blocked/unusable - blocked egress SEALS: Deteriorated/Missing Seals/Caulking/Glazing Compound (Light Around Door) EXPOSED WIRES: Unsecured cover/wires/connections creating a hazard EXPOSED WIRES: Unsecured cover/wires/connections creating a hazard COVERS: Outlet/switch has broken/loose cover plate - no exposed wires. Unit	Notes Notes Unit 215 bedroom area in unit 215 unit 215 cover on ac missing in unit 215 clamp missing unit 215 clamp missing Unit 215		L3 L3 L3 L3 L3 L1	x x x x	LT LT N/A LT	Pts 0 1.05 0.08 1.05 0.03	9:52AM Date Sep 10 2015 9:48AM Sep 10 2015 9:50AM Sep 10 2015 9:47AM Sep 10 2015 9:49AM Sep 10 2015 9:49AM	
408 N FIELDER RO Location Bedroom 1 Bedroom 1 Entry Door Health & Safety Kitchen Living Room	AD UNIT:B15 Item Smoke Detector Windows Door - Entry/Fire/Bath Health & Safety Dishwasher/Disposal Outlets/Switches	LABELS: Breakers or circuits in panel not labeled Unit Deficiency FIRE SAFETY: Smoke detector inoperable/missing EGRESS: Emergency fire exit blocked/unusable - blocked egress SEALS: Deteriorated/Missing Seals/Caulking/Glazing Compound (Light Around Door) EXPOSED WIRES: Unsecured cover/wires/connections creating a hazard COVERS: Outlet/switch has broken/loose cover plate - no exposed wires	Notes Notes Unit 215 bedroom area in unit 215 unit 215 cover on ac missing in unit 215 clamp missing in disposal		L3 L3 L3 L3 L3	x x x x	LT LT N/A LT	Pts 0 1.05 0.08 1.05 0.03	9:52AM Date Date Sep 10 2015 9:48AM Sep 10 2015 9:50AM Sep 10 2015 9:49AM Sep 10 2015 9:49AM Sep 10 2015	Fixe

408 N FIELDER RC	DAD UNIT:C23									
Location	ltem	Deficiency	Notes	Pic	Sev	HS	LT	Pts	Date	Fixed
Entire Unit	Entire Location	General Comment	Remove all outside storage in unit 223				N/A	0	Sep 10 2015 10:30AM	
		Unit								
408 N FIELDER RC	DAD UNIT:C25	Deficiency	Notes	Die	Sev	ЦС	ιт.	Dte	Date	Fixe
Location	nem			FIC	Sev	пэ	-	FIS		FIXe
Bedroom 1	Smoke Detector	FIRE SAFETY: Smoke detector inoperable/missing	Smoke detector in unit 225		L3	Х	LT	0	Sep 10 2015 10:33AM	
Patio/Porch/Balcony	Ceiling	CRACK: Crack > 1/8in. wide and 11in. long	Repair hole outside in ceiling area by unit 225		L1		N/A	0.04	Sep 10 2015 10:32AM	
		Unit								
408 N FIELDER RC	DAD UNIT:C26 Item	Deficiency	Notes	Die	Sev	ЦС	ιт.	Pts	Date	Fixe
Location	nem		Notes	FIC	964	115		r tə	Date	TINC
Bedroom 1	Smoke Detector	FIRE SAFETY: Smoke detector inoperable/missing	Unit 226		L3	х	LT	0	Sep 10 2015 9:45AM	
Halls/Corridors/Stairs	Smoke Detector	FIRE SAFETY: Smoke detector inoperable/missing	Unit 226		L3	Х	LT	0	Sep 10 2015 9:45AM	
Health & Safety	Health & Safety	INFESTATION - Insects	spray for roaches in unit 226		L3	х	NLT	0.47	Sep 10 2015 9:43AM	
Living Room	Smoke Detector	FIRE SAFETY: Smoke detector inoperable/missing	Unit 226		L3	х	LT	0	Sep 10 2015 9:45AM	
Local Systems	Electric Panel	LABELS: Breakers or circuits in panel not labeled	Unit 226				N/A	0	Sep 10 2015 9:44AM	
		Unit								
408 N FIELDER RC										
Location	DAD UNIT:D47 Item	Deficiency	Notes	Pic	Sev	HS	LT	Pts	Date	Fixe
		Deficiency HOLE: Hole and/or damaged area on ceiling > 8.5in. x 11in.	Notes repair Sheetrock and if leak still exists repair leak in unit 47	Pic	Sev	HS		Pts 0.08	Date Sep 10 2015 11:42AM	Fixe
Location	Item	HOLE: Hole and/or damaged area	repair Sheetrock and if leak still exists repair	Pic		HS	N/A		Sep 10 2015	Fixe
Location Bathroom 1	Item Ceiling	HOLE: Hole and/or damaged area on ceiling > 8.5in. x 11in. COVERS: Outlet/switch has broken/loose cover plate - no	repair Sheetrock and if leak still exists repair leak in unit 47	Pic	L2	HS	N/A N/A	0.08	Sep 10 2015 11:42AM Sep 10 2015	Fixe
Location Bathroom 1 Bedroom 1 Bedroom 2	Item Ceiling Outlets/Switches	HOLE: Hole and/or damaged area on ceiling > 8.5in. x 11in. COVERS: Outlet/switch has broken/loose cover plate - no exposed wires HOLE: Interior door has hole	repair Sheetrock and if leak still exists repair leak in unit 47 Replace cover in unit 47 repair hole in bedroom door second bedroom in	Pic	L2 L1	HS	N/A N/A N/A	0.08	Sep 10 2015 11:42AM Sep 10 2015 11:39AM Sep 10 2015	Fixe
Location Bathroom 1 Bedroom 2 Bedroom 2	Item Ceiling Outlets/Switches Door - Interior	HOLE: Hole and/or damaged area on ceiling > 8.5in. x 11in. COVERS: Outlet/switch has broken/loose cover plate - no exposed wires HOLE: Interior door has hole 1/4in 1in. COVERS: Outlet/switch has broken/loose cover plate - no	repair Sheetrock and if leak still exists repair leak in unit 47 Replace cover in unit 47 repair hole in bedroom door second bedroom in unit 47 Replace cover in second bedroom in unit	Pic	L2 L1 L2	HS	N/A N/A N/A N/A	0.08 0.03 0.07	Sep 10 2015 11:42AM Sep 10 2015 11:39AM Sep 10 2015 11:41AM Sep 10 2015	Fixe
Location Bathroom 1 Bedroom 1	Item Ceiling Outlets/Switches Door - Interior Outlets/Switches	HOLE: Hole and/or damaged area on ceiling > 8.5in. x 11in. COVERS: Outlet/switch has broken/loose cover plate - no exposed wires HOLE: Interior door has hole 1/4in 1in. COVERS: Outlet/switch has broken/loose cover plate - no exposed wires SEALS: Deteriorated/Missing Seals/Caulking/Glazing	repair Sheetrock and if leak still exists repair leak in unit 47 Replace cover in unit 47 repair hole in bedroom door second bedroom in unit 47 Replace cover in second bedroom in unit 47 unit 47 unit 47	Pic	L2 L1 L2 L1	HS X	N/A N/A N/A N/A	0.08 0.03 0.07 0.03	Sep 10 2015 11:42AM Sep 10 2015 11:39AM Sep 10 2015 11:41AM Sep 10 2015 11:40AM Sep 10 2015	Fixe
Location Bathroom 1 Bedroom 1 Bedroom 2 Bedroom 2 Entry Door	Item Ceiling Outlets/Switches Door - Interior Outlets/Switches Door - Entry/Fire/Bath	HOLE: Hole and/or damaged area on ceiling > 8.5in. x 11in. COVERS: Outlet/switch has broken/loose cover plate - no exposed wires HOLE: Interior door has hole 1/4in 1in. COVERS: Outlet/switch has broken/loose cover plate - no exposed wires SEALS: Deteriorated/Missing Seals/Caulking/Glazing Compound (Light Around Door) EXPOSED WIRES: Unsecured cover/wires/connections creating a	repair Sheetrock and if leak still exists repair leak in unit 47 Replace cover in unit 47 repair hole in bedroom door second bedroom in unit 47 Replace cover in second bedroom in unit 47 unit 47 unit 47 repair wires located on wall area in ac unit and place them under a junction box and wire	Pic	L2 L1 L2 L1		N/A N/A N/A N/A LT	0.08 0.03 0.07 0.03 0.03	Sep 10 2015 11:42AM Sep 10 2015 11:39AM Sep 10 2015 11:41AM Sep 10 2015 11:40AM Sep 10 2015 11:42AM	Fixe
Location Bathroom 1 Bedroom 1 Bedroom 2 Bedroom 2 Entry Door Health & Safety Living Room	Item Ceiling Outlets/Switches Door - Interior Outlets/Switches Door - Entry/Fire/Bath Health & Safety	HOLE: Hole and/or damaged area on ceiling > 8.5in. x 11in. COVERS: Outlet/switch has broken/loose cover plate - no exposed wires HOLE: Interior door has hole 1/4in 1in. COVERS: Outlet/switch has broken/loose cover plate - no exposed wires SEALS: Deteriorated/Missing Seals/Caulking/Glazing Compound (Light Around Door) EXPOSED WIRES: Unsecured cover/wires/connections creating a hazard HOLE: Hole/missing tile/damaged	repair Sheetrock and if leak still exists repair leak in unit 47 Replace cover in unit 47 repair hole in bedroom door second bedroom in unit 47 Replace cover in second bedroom in unit 47 unit 47 unit 47 repair wires located on wall area in ac unit and place them under a junction box and wire them correctly in unit 47 Repair hole behind front	Pic	L2 L1 L2 L3		N/A N/A N/A N/A LT	0.08 0.03 0.07 0.03 0.08	Sep 10 2015 11:42AM Sep 10 2015 11:39AM Sep 10 2015 11:41AM Sep 10 2015 11:40AM Sep 10 2015 11:42AM Sep 10 2015 11:38AM	Fixe
Location Bathroom 1 Bedroom 1 Bedroom 2 Bedroom 2 Entry Door Health & Safety	Item Ceiling Outlets/Switches Door - Interior Outlets/Switches Door - Entry/Fire/Bath Health & Safety Walls	HOLE: Hole and/or damaged area on ceiling > 8.5in. x 11in. COVERS: Outlet/switch has broken/loose cover plate - no exposed wires HOLE: Interior door has hole 1/4in 1in. COVERS: Outlet/switch has broken/loose cover plate - no exposed wires SEALS: Deteriorated/Missing Seals/Caulking/Glazing Compound (Light Around Door) EXPOSED WIRES: Unsecured cover/wires/connections creating a hazard HOLE: Hole/missing tile/damaged area 1in 8.5x11in.	repair Sheetrock and if leak still exists repair leak in unit 47 Replace cover in unit 47 repair hole in bedroom door second bedroom in unit 47 Replace cover in second bedroom in unit 47 unit 47 unit 47 repair wires located on wall area in ac unit and place them under a junction box and wire them correctly in unit 47 Repair hole behind front door area unit 47	Pic	L2 L1 L2 L3		N/A N/A N/A N/A LT	0.08 0.03 0.07 0.03 0.08 1.05	Sep 10 2015 11:42AM Sep 10 2015 11:39AM Sep 10 2015 11:41AM Sep 10 2015 11:42AM Sep 10 2015 11:38AM Sep 10 2015 11:44AM	Fixe
Location Bathroom 1 Bedroom 1 Bedroom 2 Bedroom 2 Entry Door Health & Safety Living Room	Item Ceiling Outlets/Switches Door - Interior Outlets/Switches Door - Entry/Fire/Bath Health & Safety Walls Water Heater	HOLE: Hole and/or damaged area on ceiling > 8.5in. x 11in. COVERS: Outlet/switch has broken/loose cover plate - no exposed wires HOLE: Interior door has hole 1/4in 1in. COVERS: Outlet/switch has broken/loose cover plate - no exposed wires SEALS: Deteriorated/Missing Seals/Caulking/Glazing Compound (Light Around Door) EXPOSED WIRES: Unsecured cover/wires/connections creating a hazard HOLE: Hole/missing tile/damaged area 1in 8.5x11in. General Comment	repair Sheetrock and if leak still exists repair leak in unit 47 Replace cover in unit 47 repair hole in bedroom door second bedroom in unit 47 Replace cover in second bedroom in unit 47 unit 47 unit 47 repair wires located on wall area in ac unit and place them under a junction box and wire them correctly in unit 47 Repair hole behind front door area unit 47	Pic	L2 L1 L2 L3		N/A N/A N/A N/A LT	0.08 0.03 0.07 0.03 0.08 1.05	Sep 10 2015 11:42AM Sep 10 2015 11:39AM Sep 10 2015 11:41AM Sep 10 2015 11:42AM Sep 10 2015 11:38AM Sep 10 2015 11:44AM	Fixed

					Inspe	ction R	esults:	408 N.	Fielder Road -	09/09/2015
Kitchen	Dishwasher/Disposal	cover/wires/connections creating a hazard	clamp missing unit 48		L3	Х	LT	1.05	10:21AM	
Local Systems	Electric Panel	LABELS: Breakers or circuits in panel not labeled	Unit 48				N/A	0	Sep 10 2015 10:21AM	
Local Systems	Electric Panel	EXPOSED WIRES: Gap of 1/4in. or more in a breaker row/panel	unit 248		L3	х	LT	0.7	Sep 10 2015 10:24AM	
Local Systems	HVAC System	General Comment	Repair Sheetrock in ac unit in unit 248				N/A	0	Sep 10 2015 10:24AM	
Local Systems	Water Heater	General Comment	install water heater correctly from top to bottom in unit 248				N/A	0	Sep 10 2015 10:29AM	
		Unit								
408 N FIELDER RO	AD UNIT:E50									
Location	Item	Deficiency	Notes	Pic	Sev	HS	LT	Pts	Date	Fixed
Bathroom 1	Toilet	TOILET: Fixture components are missing or damaged	Repair toilet in unit 150		L2	•	N/A	0.53	Sep 10 2015 10:01AM	
Bedroom 1	Walls	HOLE: Hole/missing tile/damaged area 1in 8.5x11in.	repair holes in wall and door areas in unit 150		L1		N/A	0.03	Sep 10 2015 10:02AM	
		Unit								
408 N FIELDER ROA	AD UNIT:E51									
Location	Item	Deficiency	Notes	Pic	Sev	HS	LT	Pts	Date	Fixed
Bathroom 1	Ceiling	CRACK: Crack > 1/8in. wide and 11in. long	unit 251		L1		N/A	0.04	Sep 10 2015 10:12AM	
Bathroom 1	Shower/Tub - Stall	BASIN: More than 50% discolored/cracked - shower can still be used	Resurface tub area in unit 251		L2		N/A	0.24	Sep 10 2015 10:11AM	
Entry Door	Door - Entry/Fire/Bath	General Comment	3"screws Unit 251				N/A	0	Sep 10 2015 10:10AM	
Kitchen	Dishwasher/Disposal	EXPOSED WIRES: Unsecured cover/wires/connections creating a hazard	unit 251 clamp missing		L3	х	LT	1.05	Sep 10 2015 10:13AM	
Local Systems	Electric Panel	LABELS: Breakers or circuits in panel not labeled	In unit 251				N/A	0	Sep 10 2015 10:12AM	
Local Systems	Electric Panel	EXPOSED WIRES: Cover is missing - exposed electrical connections	In unit 251		L3	х	LT	0.7	Sep 10 2015 10:12AM	
Patio/Porch/Balcony	Lighting	GLOBE: Light globe or Lens missing or damaged	unit 251				N/A	0	Sep 10 2015 10:14AM	
		Unit								
408 N FIELDER ROA	AD UNIT:E52									
Location	Item	Deficiency	Notes	Pic	Sev	HS	LT	Pts	Date	Fixed
Bathroom 1	Shower/Tub - Stall	BASIN: More than 50% discolored/cracked - shower can still be used	resurface tub area and caulk around tub area in unit 52		L2		N/A	0.24	Sep 10 2015 10:17AM	
Bathroom 1	Toilet	HARDWARE: Toilet/water closet cannot be flushed due to obstruction/defect	Unit 52		L3		N/A	1.05	Sep 10 2015 10:15AM	
Bathroom 2	Lighting	General Comment	Repair Sheetrock under light switch unit 52				N/A	0	Sep 10 2015 10:20AM	
Bathroom 2	Sink	LEAK: A slow leak or drip in basin/sink/associated piping - fixture still functions	faucet loose in unit 52		L1		N/A	0.16	Sep 10 2015 10:20AM	
Entry Door	Entire Location	General Comment	remove trash from front door area in unit 252				N/A	0	Sep 10 2015 10:23AM	
Kitchen	Dishwasher/Disposal	EXPOSED WIRES: Unsecured cover/wires/connections creating a hazard	Unit 52 need garbage disposal clamp		L3	х	LT	1.05	Sep 10 2015 10:19AM	

Local Systems

Water Heater

HVAC: Heater Element Access Panels Missing or Damaged

place cover on heater in unit 52

Inspection Results: 408 N. Fielder Road - 09/09/2015 0

N/A

Sep 10 2015 10:18AM

		Unit								
408 N FIELDER RC	OAD UNIT:E53									
Location	Item	Deficiency	Notes	Pic	Sev	HS	LT	Pts	Date	Fixed
Bathroom 1	Shower/Tub - Stall	BASIN: More than 50% discolored/cracked - shower can still be used	Resurface tub in unit 53		L2		N/A	0.24	Sep 10 2015 11:34AM	
Bathroom 1	Sink	MOLD/MILDEW: Evidence of air quality hazard due to mold/mildew	Replace entire sink in unit 53		L3	х	NLT	0.47	Sep 10 2015 11:29AM	
Bathroom 1	Walls	SURFACE: Bulging/buckling/sagging or problem with alignment	repair tiles behind toilet area and by tub area in unit 53		L3		N/A	0.17	Sep 10 2015 11:36AM	
Entire Unit	Housekeeping	General Comment	remove outside storage unit 53				N/A	0	Sep 10 2015 11:32AM	
Entry Door	Door - Entry/Fire/Bath	FRAME: Damage to frame/lintel/threshold/door jamb	Replace front door are in unit 53		L3		N/A	0.08	Sep 10 2015 11:36AM	
Halls/Corridors/Stairs	Smoke Detector	FIRE SAFETY: Smoke detector inoperable/missing	Unit 53		L3	х	LT	0	Sep 10 2015 11:28AM	
Halls/Corridors/Stairs	Wall Trim	TRIM: Damaged/ deteriorated trim 5-10% of wall area	Unit 53		L1		N/A	<.01	Sep 10 2015 11:33AM	
Living Room	Floor - Hard	FLOOR COVERING: More than 50% of hard floor shows wear/stains/damage	replace tile in unit 53		L3		N/A	0.17	Sep 10 2015 11:30AM	
Living Room	Smoke Detector	FIRE SAFETY: Smoke detector inoperable/missing	Unit 53		L3	х	LT	0	Sep 10 2015 11:28AM	
		Unit								
408 N FIELDER RC	AD UNIT:E55									
Location	Item	Deficiency	Notes	Pic	Sev	HS	LT	Pts	Date	Fixed
Entry Door	Accessories	General Comment	unit 55 remove outside furniture				N/A	0	Sep 10 2015 11:45AM	
Entry Door	Door - Entry/Fire/Bath	SEALS: Deteriorated/Missing Seals/Caulking/Glazing								
		Compound (Light Around Door)	unit 55		L3		N/A	0.08	Sep 10 2015 10:08AM	
Local Systems	Electric Panel		remove metal from breaker and place with the correct hardware in unit 55		L3		N/A N/A	0.08		
Local Systems	Electric Panel	Compound (Light Around Door)	remove metal from breaker and place with the correct hardware in		L3				10:08AM Sep 10 2015	
·		Compound (Light Around Door) General Comment	remove metal from breaker and place with the correct hardware in		L3				10:08AM Sep 10 2015	
·		Compound (Light Around Door) General Comment	remove metal from breaker and place with the correct hardware in	Pic	L3 Sev	HS		0	10:08AM Sep 10 2015	Fixed
408 N FIELDER RC Location	DAD UNIT:F65	Compound (Light Around Door) General Comment Unit	remove metal from breaker and place with the correct hardware in unit 55	Pic		HS X	N/A LT	0	10:08AM Sep 10 2015 10:09AM	Fixed
408 N FIELDER RC Location Bathroom 1	DAD UNIT:F65 Item	Compound (Light Around Door) General Comment Unit Deficiency WATER STAIN: Evidence of	remove metal from breaker and place with the correct hardware in unit 55 Notes Rechaulk around tub	Pic	Sev		N/A LT	0 Pts	10:08AM Sep 10 2015 10:09AM Date Sep 10 2015	Fixed
408 N FIELDER RC Location Bathroom 1 Entry Door	DAD UNIT:F65 Item Shower/Tub - Stall	Compound (Light Around Door) General Comment Unit Deficiency WATER STAIN: Evidence of leak/mold/mildew 4 sq in 1 sf	remove metal from breaker and place with the correct hardware in unit 55 Notes Rechaulk around tub area Unit 265 3" screws missing from	Pic	Sev		N/A LT NLT	0 Pts 0.12	10:08AM Sep 10 2015 10:09AM Date Sep 10 2015 9:04AM Sep 10 2015	Fixed
408 N FIELDER RC Location Bathroom 1 Entry Door Kitchen	DAD UNIT:F65 Item Shower/Tub - Stall Accessories	Compound (Light Around Door) General Comment Deficiency WATER STAIN: Evidence of leak/mold/mildew 4 sq in 1 sf General Comment	remove metal from breaker and place with the correct hardware in unit 55 Notes Rechaulk around tub area Unit 265 3" screws missing from unit 265 Check oven elements due to they are burning food when the oven is	Pic	Sev		N/A LT NLT N/A	0 Pts 0.12 0	10:08AM Sep 10 2015 10:09AM Date Sep 10 2015 9:04AM Sep 10 2015 9:30AM	Fixed
408 N FIELDER RC Location Bathroom 1 Entry Door Kitchen Living Room	DAD UNIT:F65 Item Shower/Tub - Stall Accessories Range Hood/Vent Fan	Compound (Light Around Door) General Comment Deficiency WATER STAIN: Evidence of leak/mold/mildew 4 sq in 1 sf General Comment General Comment	remove metal from breaker and place with the correct hardware in unit 55 Notes Rechaulk around tub area Unit 265 3" screws missing from unit 265 Check oven elements due to they are burning food when the oven is on 250 In unit 265	Pic	Sev L1	Х	N/A LT NLT N/A	0 Pts 0.12 0	10:08AM Sep 10 2015 10:09AM Date Date Sep 10 2015 9:04AM Sep 10 2015 9:06AM Sep 10 2015	Fixed
408 N FIELDER RC	DAD UNIT:F65 Item Shower/Tub - Stall Accessories Range Hood/Vent Fan Smoke Detector	Compound (Light Around Door) General Comment Deficiency WATER STAIN: Evidence of leak/mold/mildew 4 sq in 1 sf General Comment General Comment FIRE SAFETY: Smoke detector inoperable/missing	remove metal from breaker and place with the correct hardware in unit 55 Notes Rechaulk around tub area Unit 265 3" screws missing from unit 265 Check oven elements due to they are burning food when the oven is on 250 In unit 265 Unit 265	Pic	Sev L1	Х	N/A LT NLT N/A LT	0 Pts 0.12 0 0	10:08AM Sep 10 2015 10:09AM Date Sep 10 2015 9:04AM Sep 10 2015 9:06AM Sep 10 2015 9:06AM Sep 10 2015	Fixed

		Unit								
408 N FIELDER RO	AD UNIT:F66									
Location	Item	Deficiency	Notes	Pic	Sev	HS	LT	Pts	Date	Fixed
Entire Unit	Entire Location	General Comment	remove all window locks throughout unit 266				N/A	0	Sep 10 2015 9:40AM	
Kitchen	Dishwasher/Disposal	EXPOSED WIRES: Unsecured cover/wires/connections creating a hazard	place clam on disposal in unit 266		L3	х	LT	1.05	Sep 10 2015 9:40AM	
Local Systems	Electric Panel	LABELS: Breakers or circuits in panel not labeled	Unit 266				N/A	0	Sep 10 2015 9:38AM	
Local Systems	Electric Panel	EXPOSED WIRES: Gap of 1/4in. or more in a breaker row/panel	unit 266		L3	х	LT	0.7	Sep 10 2015 9:39AM	
Local Systems	Water Heater	HVAC: Heater Element Access Panels Missing or Damaged	Place cover on water heater In unit 266				N/A	0	Sep 10 2015 9:41AM	
Local Systems	Water Heater	HVAC: Heater Element Access Panels Missing or Damaged	repair vent in water heater closet area In unit 266				N/A	0	Sep 10 2015 9:42AM	
		Unit								
408 N FIELDER RO	AD UNIT:F68									
Location	Item	Deficiency	Notes	Pic	Sev	HS	LT	Pts	Date	Fixed
Entire Unit	Entire Location	General Comment	Replace all missing cover outlets throughout entire unit				N/A	0	Sep 10 2015 9:37AM	
Entire Unit	Housekeeping	HOUSEKEEPING: Excessive Clutter or Disorganized Area	please remove all the excessive clutter throughout your apt				N/A	0	Sep 10 2015 9:35AM	
Entry Door	Door - Entry/Fire/Bath	FRAME: Damage to frame/lintel/threshold/door jamb	Repair or replace front door area due to damaged door jamb in unit 268		L3		N/A	0.08	Sep 10 2015 9:33AM	
Entry Door	Door - Security/Storm	HARDWARE: Security door hardware, or other damage	Replace door frame, missing screws,door jam unit 268		L3	х	NLT	0.14	Sep 10 2015 7:37AM	
Health & Safety	Health & Safety	EXPOSED WIRES: Unsecured cover/wires/connections creating a hazard	place cover plate on a/c unit Unit 268		L3	х	LT	1.05	Sep 10 2015 7:36AM	
Living Room	Window Seals/Sills	SILL: Sill damaged but still operating as designed	repair broken window in living room Unit 268		L1		N/A	0.05	Sep 10 2015 9:02AM	
Local Systems	Water Heater	General Comment	remove all items from around water heater Unit 268				N/A	0	Sep 10 2015 7:35AM	
		Unit								
408 N FIELDER RO	AD UNIT:F69									
Location	Item	Deficiency	Notes	Pic	Sev	HS	LT	Pts	Date	Fixed
Kitchen	Dishwasher/Disposal	EXPOSED WIRES: Unsecured cover/wires/connections creating a hazard	needs clamp in unit 69		L3	х	LT	1.05	Sep 10 2015 10:07AM	
Local Systems	Electric Panel	LABELS: Breakers or circuits in panel not labeled	Label breaker and place missing blanks in unit 69				N/A	0	Sep 10 2015 10:07AM	
Local Systems	Electric Panel	EXPOSED WIRES: Any loose/unsecured section of a panel cover	Label breaker and place missing blanks in unit 69		L3	х	LT	0.7	Sep 10 2015 10:07AM	
		Unit								
408 N FIELDER RO	AD UNIT:F79									
Location	Item	Deficiency	Notes	Pic	Sev	HS	LT	Pts	Date	Fixed
Bedroom 1	Smoke Detector	FIRE SAFETY: Smoke detector inoperable/missing	Unit 79		L3	х	LT	0	Sep 10 2015 11:23AM	
		FIRE SAFETY: Smoke detector							Sep 10 2015	

						- the set		400 N	Fielder Deed	00/00/004
Bedroom 2	Smoke Detector	inoperable/missing	Unit 79		L3	X X	LT	408 N.	Fielder Road 11:24AM	- 09/09/201:
Entry Door	Accessories	General Comment	remove outside storage unit 79				N/A	0	Sep 10 2015 11:24AM	
Entry Door	Door - Security/Storm	General Comment	3" screws in unit 79				N/A	0	Sep 10 2015 11:23AM	
Halls/Corridors/Stairs	Smoke Detector	FIRE SAFETY: Smoke detector inoperable/missing	Unit 79		L3	х	LT	0	Sep 10 2015 11:25AM	
Health & Safety	Health & Safety	INFESTATION - Insects	spray unit 79		L3	х	NLT	0.47	Sep 10 2015 11:26AM	
Kitchen	Dishwasher/Disposal	EXPOSED WIRES: Unsecured cover/wires/connections creating a hazard	Unit 79 needs clamp		L3	x	LT	1.05	Sep 10 2015 11:25AM	
Kitchen	Sink	General Comment	Replace pipe with the correct hardware under kitchen sink in unitb79				N/A	0	Sep 10 2015 11:26AM	
Local Systems	Electric Panel	LABELS: Breakers or circuits in panel not labeled	unit 79				N/A	0	Sep 10 2015 11:23AM	
		Unit								
408 N FIELDER RO		Defici			•			Di	Det	
Location	Item	Deficiency	Notes	Pic	Sev	HS	LT	Pts	Date	Fixed
Bathroom 1	Sink	General Comment	repair pipe area in bathroom with the proper hardware not with an accordion pipe in unit 90				N/A	0	Sep 10 2015 10:05AM	
Entry Door	Accessories	General Comment	3"screws in unit 90				N/A	0	Sep 10 2015 10:03AM	
Kitchen	Dishwasher/Disposal	EXPOSED WIRES: Unsecured cover/wires/connections creating a hazard	clamp missing from disposal in unit 90		L3	х	LT	1.05	Sep 10 2015 10:03AM	
Local Systems	Electric Panel	LABELS: Breakers or circuits in panel not labeled	unit 90				N/A	0	Sep 10 2015 10:05AM	
		Unit								
408 N FIELDER RO					-					
Location	ltem	Deficiency	Notes	Pic	Sev	HS	LT	Pts	Date	Fixed
Entire Unit	Housekeeping	General Comment	remove outside storage unit 93				N/A	0	Sep 10 2015 11:14AM	
		Unit								
408 N FIELDER RO	DAD UNIT:G95									
Location	ltem	Deficiency	Notes	Pic	Sev	HS	LT	Pts	Date	Fixed
Kitchen	Dishwasher/Disposal	EXPOSED WIRES: Unsecured cover/wires/connections creating a hazard	unit 95 needs a clamp		L3	х	LT	1.05	Sep 10 2015 11:15AM	
Living Room	Outlets/Switches	COVERS: Outlet/switch has broken/loose cover plate - no exposed wires	Replace covers in living/bed room areas in unit 95		L1		N/A	0.03	Sep 10 2015 11:22AM	
Living Room	Smoke Detector	FIRE SAFETY: Smoke detector inoperable/missing	Unit 95		L3	х	LT	0	Sep 10 2015 11:22AM	
		Unit								
408 N FIELDER RO		Deficiency	Notos	Die	Ser	ЦС	1.7	Dto	Data	Fixed
Location	Item	Deficiency SEALS: Deteriorated/Missing	Notes	PIC	Sev	п5	LI	rts	Date	Fixed
Entry Door	Door - Entry/Fire/Bath	Seals/Caulking/Glazing Compound (Light Around Door)	Unit 196		L3		N/A	0.08	Sep 10 2015 9:53AM	
Kitchen	Windows	General Comment	remove thumb lock from windows in unit 196				N/A	0	Sep 10 2015 9:55AM	

		Unit								
408 N FIELDER ROA	AD UNIT:H103									
Location	Item	Deficiency	Notes	Pic	Sev	HS	LT	Pts	Date	Fixed
Entry Door	Door - Entry/Fire/Bath	SEALS: Deteriorated/Missing Seals/Caulking/Glazing Compound (Light Around Door)	unit 103		L3		N/A	0.08	Sep 10 2015 11:03AM	
Living Room	Ceiling	HOLE: Hole and/or damaged area on ceiling = 1in 8.5in. x 11in.	unit 103		L1		N/A	0.04	Sep 10 2015 11:04AM	
Local Systems	Electric Panel	LABELS: Breakers or circuits in panel not labeled	unit 103				N/A	0	Sep 10 2015 11:03AM	
		Unit								
408 N FIELDER ROA	AD UNIT:H105									
Location	ltem	Deficiency	Notes	Pic	Sev	HS	LT	Pts	Date	Fixed
Entry Door	Accessories	General Comment	remove outside storage in front of unit 105				N/A	0	Sep 10 2015 11:02AM	
		Unit								
408 N FIELDER ROA	AD UNIT:I115									
Location	ltem	Deficiency	Notes	Pic	Sev	HS	LT	Pts	Date	Fixed
Bedroom 1	Outlets/Switches	COVERS: Outlet/switch has broken/loose cover plate - no exposed wires	throughout unit 115		L1		N/A	0.03	Sep 10 2015 10:58AM	
Bedroom 1	Smoke Detector	FIRE SAFETY: Smoke detector inoperable/missing	Unit 115		L3	х	LT	0	Sep 10 2015 10:58AM	
Living Room	Smoke Detector	FIRE SAFETY: Smoke detector inoperable/missing	Unit 115		L3	х	LT	0	Sep 10 2015 10:58AM	
Local Systems	Electric Panel	General Comment	remove metal in breaker in unit 115				N/A	0	Sep 10 2015 10:59AM	
		Unit								
408 N FIELDER ROA	AD UNIT:1127	Unit								
408 N FIELDER ROA	AD UNIT:I127 <mark>Item</mark>	Unit Deficiency	Notes	Pic	Sev	HS	LT	Pts	Date	Fixed
			Notes unit 127	Pic	Sev L3	HS		Pts 0.08		Fixed
Location	ltem	Deficiency SEALS: Deteriorated/Missing Seals/Caulking/Glazing		Pic		HS			Sep 10 2015	Fixed
Location Entry Door	Item Door - Entry/Fire/Bath	Deficiency SEALS: Deteriorated/Missing Seals/Caulking/Glazing Compound (Light Around Door)	unit 127 Remove outside	Pic		HS	N/A	0.08	Sep 10 2015 11:00AM Sep 10 2015	Fixed
Location Entry Door	Item Door - Entry/Fire/Bath Entire Location	Deficiency SEALS: Deteriorated/Missing Seals/Caulking/Glazing Compound (Light Around Door) General Comment	unit 127 Remove outside	Pic		HS	N/A	0.08	Sep 10 2015 11:00AM Sep 10 2015	Fixed
Location Entry Door Entry Door	Item Door - Entry/Fire/Bath Entire Location	Deficiency SEALS: Deteriorated/Missing Seals/Caulking/Glazing Compound (Light Around Door) General Comment	unit 127 Remove outside				N/A N/A	0.08	Sep 10 2015 11:00AM Sep 10 2015	Fixed
Location Entry Door Entry Door 408 N FIELDER ROA	Item Door - Entry/Fire/Bath Entire Location AD UNIT:J139	Deficiency SEALS: Deteriorated/Missing Seals/Caulking/Glazing Compound (Light Around Door) General Comment Unit	unit 127 Remove outside storage unit 127		L3		N/A N/A	0.08	Sep 10 2015 11:00AM Sep 10 2015 11:00AM	
Location Entry Door Entry Door 408 N FIELDER RO/ Location	Item Door - Entry/Fire/Bath Entire Location AD UNIT:J139 Item	Deficiency SEALS: Deteriorated/Missing Seals/Caulking/Glazing Compound (Light Around Door) General Comment Unit Deficiency SEALS: Deteriorated/Missing Seals/Caulking/Glazing	unit 127 Remove outside storage unit 127 Notes		L3 Sev		N/A N/A LT	0.08 0 Pts	Sep 10 2015 11:00AM Sep 10 2015 11:00AM Date Sep 10 2015	
Location Entry Door 408 N FIELDER RO/ Location Entry Door	Item Door - Entry/Fire/Bath Entire Location AD UNIT:J139 Item Door - Entry/Fire/Bath	Deficiency SEALS: Deteriorated/Missing Seals/Caulking/Glazing Compound (Light Around Door) General Comment Unit Deficiency SEALS: Deteriorated/Missing Seals/Caulking/Glazing Compound (Light Around Door) FLOOR COVERING: 5-10% of hard floor shows	unit 127 Remove outside storage unit 127 Notes Unit 139		L3 Sev L3		N/A N/A LT	0.08 0 Pts 0.08	Sep 10 2015 11:00AM Sep 10 2015 11:00AM Date Sep 10 2015 10:55AM Sep 10 2015	
Location Entry Door Entry Door 408 N FIELDER ROA Location Entry Door Halls/Corridors/Stairs	Item Door - Entry/Fire/Bath Entire Location AD UNIT:J139 Item Door - Entry/Fire/Bath Floor - Hard	Deficiency SEALS: Deteriorated/Missing Seals/Caulking/Glazing Compound (Light Around Door) General Comment Unit Deficiency SEALS: Deteriorated/Missing Seals/Caulking/Glazing Compound (Light Around Door) FLOOR COVERING: 5-10% of hard floor shows wear/stains/damage FIRE SAFETY: Smoke detector	unit 127 Remove outside storage unit 127 Notes Unit 139 unit 139		L3 Sev L3	HS	N/A N/A LT N/A	0.08 0 Pts 0.08	Sep 10 2015 11:00AM Sep 10 2015 11:00AM Date Sep 10 2015 10:55AM Sep 10 2015 10:57AM	
Location Entry Door Entry Door 408 N FIELDER RO/ Location Entry Door Halls/Corridors/Stairs Living Room	Item Door - Entry/Fire/Bath Entire Location AD UNIT:J139 Item Door - Entry/Fire/Bath Floor - Hard Smoke Detector	Deficiency SEALS: Deteriorated/Missing Seals/Caulking/Glazing Compound (Light Around Door) General Comment Unit Deficiency SEALS: Deteriorated/Missing Seals/Caulking/Glazing Compound (Light Around Door) FLOOR COVERING: 5-10% of hard floor shows wear/stains/damage FIRE SAFETY: Smoke detector inoperable/missing	unit 127 Remove outside storage unit 127 Notes Unit 139 unit 139 Unit 139		L3 Sev L3	HS	N/A N/A LT N/A LT	0.08 0 Pts 0.08 0.04	Sep 10 2015 11:00AM Sep 10 2015 11:00AM Date Sep 10 2015 10:55AM Sep 10 2015 10:57AM Sep 10 2015 10:56AM	
Location Entry Door Entry Door 408 N FIELDER RO/ Location Entry Door Halls/Corridors/Stairs Living Room	Item Door - Entry/Fire/Bath Entire Location AD UNIT:J139 Item Door - Entry/Fire/Bath Floor - Entry/Fire/Bath Floor - Hard Smoke Detector Electric Panel	Deficiency SEALS: Deteriorated/Missing Seals/Caulking/Glazing Compound (Light Around Door) General Comment Unit Deficiency SEALS: Deteriorated/Missing Seals/Caulking/Glazing Compound (Light Around Door) SEALS: Deteriorated/Missing Seals/Caulking/Glazing Compound (Light Around Door) FLOOR COVERING: 5-10% of hard floor shows wear/stains/damage FIRE SAFETY: Smoke detector inoperable/missing LABELS: Breakers or circuits in panel not labeled	unit 127 Remove outside storage unit 127 Notes Unit 139 unit 139 Unit 139		L3 Sev L3	HS	N/A N/A LT N/A LT	0.08 0 Pts 0.08 0.04	Sep 10 2015 11:00AM Sep 10 2015 11:00AM Date Sep 10 2015 10:55AM Sep 10 2015 10:57AM Sep 10 2015 10:56AM	
Location Entry Door Entry Door 408 N FIELDER RO/ Location Entry Door Halls/Corridors/Stairs Local Systems	Item Door - Entry/Fire/Bath Entire Location AD UNIT:J139 Item Door - Entry/Fire/Bath Floor - Entry/Fire/Bath Floor - Hard Smoke Detector Electric Panel	Deficiency SEALS: Deteriorated/Missing Seals/Caulking/Glazing Compound (Light Around Door) General Comment Unit Deficiency SEALS: Deteriorated/Missing Seals/Caulking/Glazing Compound (Light Around Door) SEALS: Deteriorated/Missing Seals/Caulking/Glazing Compound (Light Around Door) FLOOR COVERING: 5-10% of hard floor shows wear/stains/damage FIRE SAFETY: Smoke detector inoperable/missing LABELS: Breakers or circuits in panel not labeled	unit 127 Remove outside storage unit 127 Notes Unit 139 unit 139 Unit 139	Pic	L3 Sev L3	HS	N/A N/A LT N/A LT N/A	0.08 0 Pts 0.08 0.04	Sep 10 2015 11:00AM Sep 10 2015 11:00AM Date Sep 10 2015 10:55AM Sep 10 2015 10:57AM Sep 10 2015 10:56AM	
Location Entry Door Entry Door Control	Item Door - Entry/Fire/Bath Entire Location Door - Entry/Fire/Bath Door - Entry/Fire/Bath Floor - Hard Smoke Detector Electric Panel	Deficiency SEALS: Deteriorated/Missing Seals/Caulking/Glazing Compound (Light Around Door) General Comment Unit Deficiency SEALS: Deteriorated/Missing Seals/Caulking/Glazing Compound (Light Around Door) FLOOR COVERINS: 5-10% of hard floor shows wear/stains/damage FIRE SAFETY: Smoke detector ioperable/missing LABELS: Breakers or circuits in panel not labeled	unit 127 Remove outside storage unit 127 Notes Unit 139 Unit 139 Unit 139 unit 139	Pic	L3 Sev L3 L1 L3	HS	N/A N/A LT N/A LT N/A	0.08 0 Pts 0.08 0.04 0	Sep 10 2015 11:00AM Sep 10 2015 11:00AM Date Sep 10 2015 10:55AM Sep 10 2015 10:56AM Sep 10 2015 10:56AM	Fixed

					Inspe	ction R	esults:	408 N.	Fielder Road	- 09/09/20
Entry Door	Door - Entry/Fire/Bath	Seals/Caulking/Glazing Compound (Light Around Door)	unit 149		L3		N/A	0.08	10:50AM	l
Local Systems	Electric Panel	LABELS: Breakers or circuits in panel not labeled	unit 149				N/A	0	Sep 10 2015 10:50AM	
		Unit								
408 N FIELDER RC	DAD UNIT:K150									
Location	Item	Deficiency	Notes	Pic	Sev	HS	LT	Pts	Date	Fixed
Bathroom 1	Door - Entry/Fire/Bath	HOLE: Door has hole > 1/4in.	repair hole in door area in unit 150		L3		N/A	0.14	Sep 10 2015 10:00AM	
Halls/Corridors/Stairs	Walls	HOLE: Hole/missing tile/damaged area 1in 8.5x11in.	fix hole in wall area In unit 150		L1		N/A	0.03	Sep 10 2015 9:59AM	
Patio/Porch/Balcony	Housekeeping	General Comment	Remove TV from front porch area in unit 150				N/A	0	Sep 10 2015 9:58AM	
		Unit								
408 N FIELDER RC	DAD UNIT:K157									
Location	ltem	Deficiency	Notes	Pic	Sev	HS	LT	Pts	Date	Fixed
Patio/Porch/Balcony	Housekeeping	HOUSEKEEPING: Excessive Clutter or Disorganized Area	Make sure all firewood is stacked 12" from the ground in unit 157				N/A	0	Sep 10 2015 10:47AM	
		Unit								
408 N FIELDER RC							_			
Location	Item	Deficiency	Notes	Pic	Sev	HS	LT	Pts	Date	Fixe
Entire Unit	Entire Location	General Comment	Remove outside storage unit 159				N/A	0	Sep 10 2015 10:46AM	
		Unit								
408 N FIELDER RC	DAD UNIT:L163									
Location	ltem	Deficiency	Notes	Pic	Sev	HS	LT	Pts	Date	Fixe
Entire Unit	Entire Location	General Comment	Repair base boards and fix wall area in unit 163				N/A	0	Sep 10 2015 9:57AM	
Local Systems	Electric Panel	General Comment	remove metal blanks from breaker box in unit 163				N/A	0	Sep 10 2015 9:56AM	
		Unit								
408 N FIELDER RC	OAD UNIT:L164									
Location	ltem	Deficiency	Notes	Pic	Sev	HS	LT	Pts	Date	Fixed
Entire Unit	Entire Location	General Comment	remove outside storage in unit 164				N/A	0	Sep 10 2015 10:48AM	
		Unit								
408 N FIELDER RC	OAD UNIT:L167									
Location	ltem	Deficiency	Notes	Pic	Sev	HS	LT	Pts	Date	Fixed
Entire Unit	Housekeeping	General Comment	Remove outside storage unit 167				N/A	0	Sep 10 2015 10:48AM	
		Unit								
408 N FIELDER RC	OAD UNIT:M195									
Location	ltem	Deficiency	Notes	Pic	Sev	HS	LT	Pts	Date	Fixe
		HOLE: Interior door has hole	Hole behind door area unit 195		L2		N/A	0.07	Sep 10 2015 10:44AM	
Living Room	Door - Interior	1/4in 1in.								
Living Room Living Room	Floor - Soft	FLOOR COVERING: 5-10% of soft floor covering shows wear/stains/damage	repair carpet		L1		N/A	0.04	Sep 10 2015 10:40AM	

408 N FIELDER ROAD UNIT:M197									
Location	ltem	Deficiency	Notes	Pic Sev	HS	LT	Pts	Date	Fixed
Entire Unit	Entire Location	General Comment	Remove outside storage unit 197			N/A	0	Sep 10 2015 10:45AM	

Date 11/15/2016 Type Pre-REAC Score 91

Area	*Pts.Lost(Raw)	*Pts. Lost(Adj.)	*Pts. Lost(Cap)	Poss. Points	Score	Violations
Site	0	0	0	15	15	3
Exterior	0	0	0	15	15	7
Systems	0	0	0	20	20	0
Common	1.49	1.49	1.49	15	13.51	24
*Units	30	30	30	35	27.5	11
Total	31.49	31.49	8.99	100	91.01	45

Pts. Lost (Raw) is the total point loss of all findings before the application of HUD scoring rules

Pts. Lost (Adj.) is the raw point loss adjusted for multiple findings of the same violation in the same building/unit per HUD rules

Pts. Lost (Cap) is the adjusted point loss capped by the maximum possible point loss of each building/unit per HUD rules

 $^{\star}\textsc{Units}$ Area Score is projected for the REAC sample size based on the average unit score *

		Entire Si	te							
Site										
Location	Item	Deficiency	Notes	Pic	Sev	HS	LT	Pts	Date	Fixed
Entire Area	Entire Site	General Comment	Properly secure cable boxes throughout property				N/A	0	Nov 15 2016 10:35AM	
Health & Safety	Health & Safety	General Comment	Remove all improperly stored items on porches and walkways				N/A	0	Nov 15 2016 10:34AM	
Licenses and Permits	Multifamily License	CERTIFICATION: Missing/Expired/or Not Displayed	Complete Multi Family License Application				N/A	0	Nov 15 2016 10:34AM	
		Exterio	r							
16										
Location	Item	Deficiency	Notes	Pic	Sev	HS	LT	Pts	Date	Fixed
Exterior Walls	Entire Location	General Comment	Paint wooden phone box cover				N/A	0	Nov 15 2016 10:49AM	
		Exterio	r							
19										
Location	Item	Deficiency	Notes	Pic	Sev	HS	LT	Pts	Date	Fixed
Exterior Walls	Entire Location	General Comment	And you wooden phone box cover				N/A	0	Nov 15 2016 10:51AM	
		Exterio	r							
20										
Location	Item	Deficiency	Notes	Pic	Sev	HS	LT	Pts	Date	Fixed
Exterior Walls	Walls	General Comment	Cover the whole west side of building				N/A	0	Nov 15 2016 10:59AM	
Exterior Walls	Walls	General Comment	Paint wood phone box cover				N/A	0	Nov 15 2016 11:00AM	
Exterior Walls	Walls	General Comment	Remove wasp nest apartment 280 window				N/A	0	Nov 15 2016 11:00AM	
		Exterio	r							
5										
Location	Item	Deficiency	Notes	Pic	Sev	HS	LT	Pts	Date	Fixed
Exterior Walls	Entire Location	General Comment	Paint raw wood cover for phone box				N/A	0	Nov 15 2016 10:40AM	

)		Exterio	r							
Location	ltem	Deficiency	Notes	Pic	Sev	HS	LT	Pts	Date	Fixed
xterior Walls	Entire Location	General Comment	Paint Phone box cover				N/A	0	Nov 15 2016 10:43AM	
		Common A	Area							
Location	ltem	Deficiency	Notes	Pic	Sev	HS	ιт	Pts	Date	Fixe
Patio/Porch/Balcony	Baluster/Side Railing	SIDE RAILS: The baluster or side railing is loose or damaged	Properly install lag bolts where missing and tighten lag bolts that are loose on guard rails and hand rails and top step brackets		L3			0.08	Nov 15 2016 10:24AM	
		Common A	Area							
1 Location	ltem	Deficiency	Notes	Pic	Sev	нс	ιт	Pte	Date	Fixe
Patio/Porch/Balcony	Baluster/Side Railing	SIDE RAILS: The baluster or side railing is loose or damaged	Properly install lag bolts where missing and tighten lag bolts that are loose on guard rails and hand rails and top step brackets		L3			0.08	Nov 15 2016 10:24AM	
		Common A	Area							
2 Location	ltem	Deficiency	Notes	Pic	Sev	HS	LT	Pts	Date	Fixe
atio/Porch/Balcony	Baluster/Side Railing	SIDE RAILS: The baluster or side railing is loose or damaged	Properly install lag bolts where missing and tighten lag bolts that are loose on guard rails and hand rails and top step brackets		L3		NLT	0.08	Nov 15 2016 10:25AM	
		Common A	Area							
3 Location	Item	Deficiency	Notes	Pic	Sev	ня	ιт	Pts	Date	Fixe
atio/Porch/Balcony	Baluster/Side Railing	SIDE RAILS: The baluster or side railing is loose or damaged	Properly install lag bolts where missing and tighten lag bolts that are loose on guard rails and hand rails and top step brackets		L3			0.08	Nov 15 2016 10:25AM	
		Common A	Area							
4 Location	ltem	Deficiency	Notes	Pic	Sev	нс	ιт	Pts	Date	Fixe
atio/Porch/Balcony	Baluster/Side Railing	SIDE RAILS: The baluster or side railing is loose or damaged	Properly install lag bolts where missing and tighten lag bolts that are loose on guard rails and hand rails and top step brackets		L3			0.08	Nov 15 2016 10:25AM	. 176
		Common A	Area							
5 Location	ltem	Deficiency	Notes	Pic	Sev	HS	LT	Pts	Date	Fixe
atio/Porch/Balcony	Baluster/Side Railing	SIDE RAILS: The baluster or side railing is loose or damaged	Properly install lag bolts where missing and tighten lag bolts that are loose on guard rails and hand rails and top step brackets		L3		NLT	0.08	Nov 15 2016 10:26AM	
Patio/Porch/Balcony	Baluster/Side Railing		loose on guard rails and hand rails and top step brackets		L3		NLT	0.08		

					Inspe	ection R	esults:	408 N.	Fielder Road	- 11/15/2016
Location	ltem	Deficiency	Notes	Pic	Sev	HS	LT	Pts	Date	Fixed
Patio/Porch/Balcony	Baluster/Side Railing	SIDE RAILS: The baluster or side railing is loose or damaged	Properly install lag bolts where missing and tighten lag bolts that are loose on guard rails and hand rails and top step brackets		L3		NLT	0.08	Nov 15 2016 10:26AM	
		Common /	Area							
18										
Location	Item	Deficiency	Notes	Pic	Sev	HS	LT	Pts	Date	Fixed
Patio/Porch/Balcony	Baluster/Side Railing	SIDE RAILS: The baluster or side railing is loose or damaged	Properly install lag bolts where missing and tighten lag bolts that are loose on guard rails and hand rails and top step brackets		L3		NLT	0.08	Nov 15 2016 10:27AM	
Patio/Porch/Balcony	Walls	PAINT: Peeling / deteriorated / missing paint/non-workmanlike repair affecting > 4sf	Replace rotted wood scraped cheerier rated paint prime and paint balcony areas between 228 and 227		L2		N/A	<.01	Nov 15 2016 10:50AM	
		Common /	Area							
19										
Location	Item	Deficiency	Notes	Pic	Sev	HS	LT	Pts	Date	Fixed
Patio/Porch/Balcony	Baluster/Side Railing	SIDE RAILS: The baluster or side railing is loose or damaged	Properly install lag bolts where missing and tighten lag bolts that are loose on guard rails and hand rails and top step brackets		L3		NLT	0.08	Nov 15 2016 10:27AM	
		Common /	Area							
2			liou							
Location	Item	Deficiency	Notes	Pic	Sev	HS	LT	Pts	Date	Fixed
Patio/Porch/Balcony	Baluster/Side Railing	SIDE RAILS: The baluster or side railing is loose or damaged	Properly install lag bolts where missing and tighten lag bolts that are loose on guard rails and hand rails and top step brackets		L3		NLT	0.08	Nov 15 2016 10:28AM	
Patio/Porch/Balcony	Walls	PAINT: Peeling / deteriorated / missing paint/non-workmanlike repair affecting > 4sf	Replace rotted wood on balcony between9 and 10 scrape deteriorated paint prime and paint to match		L2		N/A	<.01	Nov 15 2016 10:37AM	
		Common /	Area							
20										
Location	ltem	Deficiency	Notes	Pic	Sev	HS	LT	Pts	Date	Fixed
Patio/Porch/Balcony	Baluster/Side Railing	SIDE RAILS: The baluster or side railing is loose or damaged	Properly install lag bolts where missing and tighten lag bolts that are loose on guard rails and hand rails and top step brackets		L3		NLT	0.08	Nov 15 2016 10:29AM	
Patio/Porch/Balcony	Walls	PAINT: Peeling / deteriorated / missing paint/non-workmanlike repair affecting > 4sf	Replace rotted wood scrape deteriorated paint prime and paint to match balcony areas apartment 277 and 278 and 279 and 280		L2		N/A	<.01	Nov 15 2016 11:01AM	
		Common /	Area							
4										
Location	ltem	Deficiency	Notes	Pic	Sev	HS	LT	Pts	Date	Fixed
		SIDE RAILS: The baluster or side	Properly install lag bolts where missing and tighten lag bolts that are						Nov 15 2016	

Patio/Porch/Balcony

Baluster/Side Railing

railing is loose or damaged

loose on guard rails and hand rails and top step
 Inspection Results:
 408 N. Fielder Road - 11/15/2016

 L3
 NLT
 0.08
 10:29AM

			hand rails and top step brackets							
		Common A	Area							
5					_			_	_	
Location	Item	Deficiency	Notes	Pic	Sev	HS	LT	Pts	Date	Fixed
Patio/Porch/Balcony	Baluster/Side Railing	SIDE RAILS: The baluster or side railing is loose or damaged	Properly install lag bolts where missing and tighten lag bolts that are loose on guard rails and hand rails and top step brackets		L3		NLT	0.08	Nov 15 2016 10:29AM	
Patio/Porch/Balcony	Ceiling	PAINT: Peeling / deteriorated / missing paint/non-workmanlike repair affecting > 4sf	Replace rotted wood scrape deteriorated paint prime and paint over head by apartment 33		L2		N/A	<.01	Nov 15 2016 10:41AM	
		Common A	Area							
6										
Location	ltem	Deficiency	Notes	Pic	Sev	HS	LT	Pts	Date	Fixed
Patio/Porch/Balcony	Baluster/Side Railing	SIDE RAILS: The baluster or side railing is loose or damaged	Properly install lag bolts where missing and tighten lag bolts that are loose on guard rails and hand rails and top step brackets		L3		NLT	0.08	Nov 15 2016 10:30AM	
Patio/Porch/Balcony	Walls	PAINT: Peeling / deteriorated / missing paint/non-workmanlike repair affecting > 4sf	Replace rotted wood scraped deteriorated paint prime and paint balcony facia apartment between 49 and 50		L2		N/A	<.01	Nov 15 2016 10:43AM	
		Common A	Area							
7										
Location	ltem	Deficiency	Notes	Pic	Sev	HS	LT	Pts	Date	Fixed
Patio/Porch/Balcony	Baluster/Side Railing	SIDE RAILS: The baluster or side railing is loose or damaged	Properly install lag bolts where missing and tighten lag bolts that are loose on guard rails and hand rails and top step brackets		L3		NLT	0.08	Nov 15 2016 10:30AM	
		Common A	Area							
3										
Location	ltem	Deficiency	Notes	Pic	Sev	HS	LT	Pts	Date	Fixed
Patio/Porch/Balcony	Baluster/Side Railing	SIDE RAILS: The baluster or side railing is loose or damaged	Properly install lag bolts where missing and tighten lag bolts that are loose on guard rails and hand rails and top step brackets		L3		NLT	0.08	Nov 15 2016 10:31AM	
		Common A	Area							
)										
Location	ltem	Deficiency	Notes	Pic	Sev	HS	LT	Pts	Date	Fixed
Patio/Porch/Balcony	Baluster/Side Railing	SIDE RAILS: The baluster or side railing is loose or damaged	Properly install lag bolts where missing and tighten lag bolts that are loose on guard rails and hand rails and top step brackets		L3		NLT	0.08	Nov 15 2016 10:31AM	
Patio/Porch/Balcony	Lighting	General Comment	Replace exterior light between apartment 106 and 108				N/A	0	Nov 15 2016 10:46AM	
Patio/Porch/Balcony	Walls	PAINT: Peeling / deteriorated / missing paint/non-workmanlike repair affecting > 4sf	Replace rotted wood great picture your paint prime and paint balcony areas between apartment 101 and 102		L2		N/A	<.01	Nov 15 2016 10:44AM	

		Unit								
16 UNIT:204										
Location	ltem	Deficiency	Notes	Pic	Sev	HS	LT	Pts	Date	Fixed
Entry Door	Accessories	HARDWARE: Missing or Damaged Door Knocker or Peep Hole	Replace peep hole				N/A	0	Nov 15 2016 10:48AM	
Local Systems	Electric Panel	LABELS: Breakers or circuits in panel not labeled	Label breakers				N/A	0	Nov 15 2016 10:48AM	
		Unit								
20 UNIT:262										
Location	ltem	Deficiency	Notes	Pic	Sev	HS	LT	Pts	Date	Fixed
Bathroom 1	Shower/Tub - Hardware	General Comment	Secure overflow cover hall bathroom tub				N/A	0	Nov 15 2016 10:55AM	
Bathroom 1	Shower/Tub - Stall	General Comment	Ensure all of the drain does not leak into bottom unit				N/A	0	Nov 15 2016 10:58AM	
Bathroom 1	Sink	SINK: Basin has cracks or discoloration in more than 50% of the area	Resurface or replace hall bathroom sink		L1		N/A	5	Nov 15 2016 10:56AM	
Bathroom 1	Walls	General Comment	Properly repair whole bathroom wall texture paint to match				N/A	0	Nov 15 2016 10:59AM	
Bathroom 2	Toilet	HARDWARE: Toilet continuously running	Repair master bathroom toilet not to run		L2	x	NLT	5	Nov 15 2016 10:57AM	
Bedroom 2	Windows	LOCK: Inoperable/not locking - lock is broken but window is secure	Replace missing window latch master bedroom		L1		N/A	5	Nov 15 2016 10:57AM	
Kitchen	Dishwasher/Disposal	DISPOSAL: Garbage disposal does not function properly	Repair replace disposal		L2		N/A	5	Nov 15 2016 10:56AM	
		Unit								
20 UNIT:274										
Location	ltem	Deficiency	Notes	Pic	Sev	HS	LT	Pts	Date	Fixed
Living Room	Windows	PANES: Cracked or broken window panes - no sharp edges	Replace cracked window	_	L1	_	N/A	5	Nov 15 2016 11:02AM	
		Unit								
5 UNIT:41										
Location	Item	Deficiency	Notes	Pic	Sev	HS	LT	Pts	Date	Fixed
Living Room	Windows	PANES: Cracked or broken window panes - no sharp edges	Replace cracked window pane		L1		N/A	5	Nov 15 2016 10:38AM	

Date 10/30/2017

Type Pre-REAC

Score 96

Area	*Pts.Lost(Raw)	*Pts. Lost(Adj.)	*Pts. Lost(Cap)	Poss. Points	Score	Violations
Site	0	0	0	15	15	0
Exterior	0	0	0	15	15	0
Systems	0.39	0.39	0.39	20	19.61	1
Common	0	0	0	15	15	0
*Units	2.1	2.1	2.1	35	30.96	2
Total	2.49	2.49	4.43	100	95.57	3

Pts. Lost (Raw) is the total point loss of all findings before the application of HUD scoring rules *Pts. Lost (Adj.) is the raw point loss adjusted for multiple findings of the same violation in the same building/unit per HUD rules* *Pts. Lost (Cap) is the adjusted point loss capped by the maximum possible point loss of each building/unit per HUD rules* *Units Area Score is projected for the REAC sample size based on the average unit score*

Systems												
1												
Location	Iten	n	Defi	ciency	Notes	Pic	Sev	HS	LT	Pts	Date	Fixed
Fire Protection Extinguisher		opera	SAFETY: No ble/unexpired extinguisher ch floor	Devices are required to be scheduled for certification annually.	1	L3	х	LT	0.39	Oct 30 2017 10:03AM		
	1 Systems Totals											
Violations: 1 Possible Pts.: 0.50				Pts. Lost: 0.39 (0.	39 Raw/0.39 Adj./0.39	9 Cap))	Pts.	Reta	ained:	0.113	

Unit										
11 Unit 120										
Location	Item	Deficiency	Notes	Pic	Sev	HS	LT	Pts	Date	Fixed
Entire Unit	No Issues/Vio	lations No observed do unit	eficiencies in entire						Oct 30 2017 11:00AM	
			11 Unit 120 Totals							
	Violations: 0	Possible Pts.: 1.4	Pts. Lost: 0 (0 Raw/0 Adj./0 0	Cap)	Pts. R	letair	ned:	1.4		

			Unit							
11 Unit 123										
Location	Item	Deficiency	Notes	Pic	Sev	HS	LT	Pts	Date	Fixed
Entire Unit	No Issues/Vio	lations No observed o unit	leficiencies in entire						Oct 30 2017 11:03AM	
			11 Unit 123 Totals							
	Violations: 0	Possible Pts.: 1.4	Pts. Lost: 0 (0 Raw/0 Adj./0 0	Cap)	Pts. F	Retai	ned:	1.4		

				Unit								
13 Unit 1	56											
Location	Item	n	Defici	ency	Notes	Pic	Sev	HS	LT	Pts	Date	Fixed
Kitchen	Dishwasher/Disposal EXPOSED WIRES: Unsecured cover/wires/connections creating a hazard		Electricals security clamp missing.	2	L3	х	LT	1.05	Oct 30 2017 11:07AM	-		
				13 Unit 156 T	otals							
	Violations: 1	Possible Pts	.: 1.4	Pts. Lost: 1.05 (1.0	5 Raw/1.05 Adj./1.	05 Cap)	Pts.	Reta	ined:	0.35	

			Unit							
14 Unit 167	Itom	Deficionav	Notos	Die	Sou	ЦС	1.7	Pto	Data	Fixe
Location	Item	Deficiency	Notes	PIC	Sev	пЭ	LI	rts	Date	Fixe
Entire Unit	No Issues/Violations	No observed deficie unit	encies in entire						Oct 30 2017 11:12AM	
		14	4 Unit 167 Totals							
	Violations: 0 Pos	ssible Pts.: 1.4	Pts. Lost: 0 (0 Raw/0 Adj./0 Ca	p)	Pts. I	Retai	ned:	1.4		
			Unit							
2 Unit 11										
Location	Item	Deficiency	Notes	Pic	Sev	HS	LT	Pts	Date	Fixe
Entire Unit	No Issues/Violations	No observed deficie unit	encies in entire						Oct 30 2017 10:19AM	
			2 Unit 11 Totals							
	Violations: 0 Pos	ssible Pts.: 1.4	Pts. Lost: 0 (0 Raw/0 Adj./0 Ca	p)	Pts. I	Retai	ned:	1.4		
			Unit							
4 Unit 18										
Location	ltem	Deficiency	Notes	Pic	Sev	HS	LT	Pts	Date	Fixe
Entire Unit	No Issues/Violations	No observed deficie unit	encies in entire						Oct 30 2017 10:14AM	
			4 Unit 18 Totals							
	Violations: 0 Pos	ssible Pts.: 1.4	Pts. Lost: 0 (0 Raw/0 Adj./0 Ca	p)	Pts. I	Retai	ned:	1.4		
			Unit							
4 Unit 25			Onit							
Location	Item	Deficiency	Notes	Pic	Sev	HS	LT	Pts	Date	Fixe
Entire Unit	No Issues/Violations	No observed deficie	encies in entire						Oct 30 2017 10:25AM	
			4 Unit 25 Totals							
	Violations: 0 Pos	ssible Pts.: 1.4	Pts. Lost: 0 (0 Raw/0 Adj./0 Ca	p)	Pts. I	Retai	ned:	1.4		
			Unit							
4 Unit 27										
Location	Item	Deficiency	Notes	Pic	Sev	HS	LT	Pts	Date	Fixe
Kitchen	Dishwasher/Disposal	EXPOSED WIRES cover/wires/connec hazard	: Unsecured Appliance requires tions creating a electrical connection fo service wire pigtail.	or <u>3</u>	L3	х	LT	1.05	Oct 30 2017 10:28AM	
			4 Unit 27 Totals							
Viol	ations: 1 Possible F		ost: 1.05 (1.05 Raw/1.05 Adj./1.0	05 Cap)	Pts.	Reta	ined:	0.35	
			Unit							
5 Unit 38										
Location	Item	Deficiency	Notes	Pic	Sev	HS	LT	Pts	Date	Fixe
Location	· · · · · · · · · · · · · · · · · · ·				-					

			5 Unit 38 T	otals							
	Violations: 0	Possible Pts.: 1.4	Pts. Lost: 0	(0 Raw/0 Adj./0 Cap)		Pts. I	Retai	ned:	1.4		
			Unit								
5 Unit 41											
Location	Item	Deficiency		Notes	Pic	Sev	HS	LT	Pts	Date	Fixed
Entire Unit	No Issues/Viola	tions No observed def unit	iciencies in entire							Oct 30 2017 10:39AM	
			5 Unit 41 T	otals							
	Violations: 0	Possible Pts.: 1.4	Pts. Lost: 0	(0 Raw/0 Adj./0 Cap))	Pts. I	Retai	ned:	1.4		
			Unit								
5 Unit 45											
Location	Item	Deficiency		Notes	Pic	Sev	HS	LT	Pts	Date	Fixed
Entire Unit	No Issues/Viola	tions No observed def unit	iciencies in entire							Oct 30 2017 10:43AM	
			5 Unit 45 T	otals							
	Violations: 0	Possible Pts.: 1.4	Pts. Lost: 0	(0 Raw/0 Adj./0 Cap)		Pts. I	Retai	ned:	1.4		
			Unit								
6 Unit 50											
Location	Item	Deficiency		Notes	Pic	Sev	HS	LT	Pts	Date	Fixed
Entire Unit	No Issues/Viola	ntions No observed def unit	iciencies in entire							Oct 30 2017 10:46AM	
			6 Unit 50 T	otals							
	Violations: 0	Possible Pts.: 1.4	Pts. Lost: 0	(0 Raw/0 Adj./0 Cap))	Pts. I	Retai	ned:	1.4		
			Unit								
9 Unit 106											
Location	Item	Deficiency		Notes	Pic	Sev	HS	LT	Pts	Date	Fixed
Local Systems	HVAC System	DUCTS: Damage duct enclosure	e/gaps in HVAC	Properly secured air duct in HVAC closet.	<u>4</u>					Oct 30 2017 10:54AM	
			9 Unit 106 1	otals							
	Violations: 0	Possible Pts.: 1.4	Pts. Lost: 0	(0 Raw/0 Adj./0 Cap))	Pts. I	Retai	ned:	1.4		

Inspection Photos


Systems




. 1 Fire Protection - Extinguisher



2 13 Unit 156 Kitchen - Dishwasher/Disposal



3 4 Unit 27 Kitchen - Dishwasher/Disposal



4 9 Unit 106 Local Systems - HVAC System

Date 12/21/2018

Type Pre-REAC

Score 94

Area	*Pts.Lost(Raw)	*Pts. Lost(Adj.)	*Pts. Lost(Cap)	Poss. Points	Score	Violations
Site	1.91	1.91	1.91	15	13.09	1
Exterior	0.28	0.28	0.28	15	14.72	1
Systems	0.97	0.97	0.97	20	19.03	1
Common	0.11	0.11	0.11	15	14.89	2
*Units	0.85	0.85	0.85	35	31.95	7
Total	4.13	4.13	6.32	100	93.68	12

Pts. Lost (Raw) is the total point loss of all findings before the application of HUD scoring rules *Pts. Lost (Adj.) is the raw point loss adjusted for multiple findings of the same violation in the same building/unit per HUD rules* *Pts. Lost (Cap) is the adjusted point loss capped by the maximum possible point loss of each building/unit per HUD rules* *Units Area Score is projected for the REAC sample size based on the average unit score*

Entire Site										
Site										
Location	Item	Deficiency	Notes	Pic	Sev	HS	LT	Pts	Date	Fixed
Roads/Parking/Curbs	Roads/Parking/Curbs	POTHOLES: Potholes/loose materials causing exposed subsurface - No Hazards	Repair pothole between buildings 4 and 5	1	L2	-	-	1.91	Dec 21 2018 8:56AM	
		Site To	tals							
Violations: 1	Possible Pts.: 15	9 Pts. Lost: 1.913 (1.9	13 Raw/1.913 Adj./1.91	3 Ca	c)	Pts	Reta	ained	: 13.088	

			Exte	rior							
10											
Location	Item	Deficiency	,	Notes	Pic	Sev	HS	LT	Pts	Date	Fixed
Entire Building	Entire Loca	Observation fo Location (See		When time permits please begin a maintenance plan of replacing any damage or deteriorating exterior wall coverings						Dec 21 2018 9:35AM	
			10 Exterio	or Totals							
	Violations: 0	Possible Pts.: 0.349	Pts. Lost	: 0 (0 Raw/0 Adj./0 Cap)		Pts. F	Retaiı	ned:	0.349)	

			Exter	ior							
11											
Location	ltem	Deficiency		Notes	Pic	Sev	HS	LT	Pts	Date	Fixed
Entire Building	Entire Loca	ation Observation for Location (See N		Ensure weather protection is properly covering the area by 6	<u>2</u>					Dec 21 2018 8:40AM	
			11 Exterio	r Totals							
	Violations: 0	Possible Pts.: 1.508	Pts. Lost:	0 (0 Raw/0 Adj./0 Cap)		Pts. F	Retaiı	ned:	1.508	3	

		Exterio	r							
8										
Location	ltem	Deficiency	Notes	Pic	Sev	HS	LT	Pts	Date	Fixed
Exterior Walls	Walls	CRACK: Cracks/gaps > 1/8in.w x 1/8in.d x 6in.l	Repair hole near roof Between units 89 and 87	<u>3</u>	L2			0.28	Dec 21 2018 9:12AM	

(8 Exterior continued)										
		8 Exterior T				_				
Violations: 1	Possible Pts.:	0.754 Pts. Lost: 0.281 (0.2	81 Raw/0.281 Adj./0.2	281 (;ap)	+	'ts. R	etaine	ed: 0.473	
		Exterio	r							
9										
Location	Item	Deficiency	Notes	Pic	Sev	HS	LT	Pts	Date	Fixed
Entire Building	Entire Location	Observation for the Entire Location (See Note)	Repair damaged materials by unit 183	<u>4</u>					Dec 21 2018 9:24AM	
		9 Exterior T	otals							
Viol	ations: 0 Possi	ble Pts.: 0.754 Pts. Lost: 0	(0 Raw/0 Adj./0 Cap)		Pts. F	Retai	ned:	0.754		
		C								
20		System	5							
Location	Item	Deficiency	Notes	Pic	Sev	HS	LT	Pts	Date	Fixed
Sanitary System	Pipes/drains	DRAIN: Broken, leaking, or clogged pipes or drains	Please make plumbing repairs and clean up sewage spill behind building 20		L3	x	NLT	0.97	Dec 21 2018 9:43AM	
		20 Systems	Totals							
Violations: 1	Possible Pts.:	1.257 Pts. Lost: 0.974 (0.9	74 Raw/0.974 Adj./0.9	974 C	Cap)	P	'ts. R	etaine	ed: 0.283	
1		Common <i>i</i>	Area							
Location	ltem	Deficiency	Notes	Pic	Sev	HS	LT	Pts	Date	Fixed
Laundry Room	Accessories	ACCESSORIES: Closet Shelving Unit or Clothing Rod Damaged or Missing	Missing fire extinguisher in laundry room	<u>5</u>	-	1	1		Dec 21 2018 8:44AM	
Laundry Room	Windows	LOCK: Inoperable/not locking - lock is broken but window is secure	Replace miss glass in laundry room	<u>6</u>	L1			0.02	Dec 21 2018 8:42AM	
Laundry Room	Windows	PANES: Cracked or broken window panes	Replace miss glass in laundry room		L3	х	NLT	0.08	Dec 21 2018 8:42AM	
		1 Common Are	a Totals							
Violations: 2	Possible Pts.:	0.377 Pts. Lost: 0.106 (0.1	06 Raw/0.106 Adj./0. ⁻	106 C	Cap)	P	'ts. R	etaine	ed: 0.271	
15 Unit 192		Unit								
Location	ltem	Deficiency	Notes	Pic	Sev	HS	LT	Pts	Date	Fixed
			Repair damaged	_	L2			0.08	Dec 21 2018 9:28AM	
Patio/Porch/Balcony	Ceiling	HOLE: Hole and/or damaged area on ceiling > 8.5in. x 11in.	materials by unit 192	<u>7</u>	LZ					
Patio/Porch/Balcony	Ceiling		materials by unit 192	<u>7</u>						
Patio/Porch/Balcony Violations:		on ceiling > 8.5in. x 11in. 15 Unit 192	materials by unit 192			Pt	s. Re	taine	d: 1.316	
		on ceiling > 8.5in. x 11in. 15 Unit 192 : 1.4 Pts. Lost: 0.084 (0.08	materials by unit 192			Pt	s. Re	taine	d: 1.316	
Violations:		on ceiling > 8.5in. x 11in. 15 Unit 192	materials by unit 192			Pt	s. Re	taine	d: 1.316	
		on ceiling > 8.5in. x 11in. 15 Unit 192 : 1.4 Pts. Lost: 0.084 (0.08	materials by unit 192	34 Ca					d: 1.316 Date	Fixed

		20 Unit 277 1								
Violations: 1	Possible Pts.: 1.4	4 Pts. Lost: 0.473 (0.473	3 Raw/0.473 Adj./0.47	73 Ca	ap)	Pts	s. Re	taineo	1: 0.928	
		Unit								
4 Unit 19										
Location	Item	Deficiency	Notes	Pic	Sev	HS	LT	Pts	Date	Fixed
Living Room	Windows	PANES: Cracked or broken window panes	Replace broken window	<u>9</u>	L3	х	NLT	0.14	Dec 21 2018 8:48AM	
		4 Unit 19 To	otals							
Violations: 1	Possible Pts.: 1.4	4 Pts. Lost: 0.142 (0.142	2 Raw/0.142 Adj./0.14	42 Ca	ap)	Pts	s. Re	taineo	1: 1.258	
		Unit								
5 Unit 39	Itom	Deficiency	Notos	Die	Sav	це		Dto	Data	Fixe
Location	Item	Deficiency	Notes	FIC	Sev	13	LI	115	Date	Fixed
Living Room	Windows	PANES: Cracked or broken window panes - no sharp edges	Repair or replace window	<u>10</u>	L1			0.04	Dec 21 2018 8:58AM	
		5 Unit 39 To	otals							
Violations: 1	Possible Pts.: 1.4	4 Pts. Lost: 0.035 (0.035	5 Raw/0.035 Adj./0.03	35 Ca	ap)	Pts	s. Re	taineo	1: 1.365	
		Unit								
8 Unit 91										
Location	Item	Deficiency	Notes	Pic	Sev	HS	LT	Pts	Date	Fixe
Patio/Porch/Balcony	Ceiling	HOLE: Hole, damaged, non- workmanlike repair on ceiling from 1in 8.5in. x 11in.	Replace or repair damage balcony outside of unit	<u>11</u>	L1			0.04	Dec 21 2018 9:09AM	
		8 Unit 91 To	otals							
Violations: 1	Possible Pts.: 1.4	4 Pts. Lost: 0.042 (0.042	2 Raw/0.042 Adj./0.04	42 Ca	ap)	Pts	s. Re	taineo	1: 1.358	
		Unit								
9 Unit 104										
Location	Item	Deficiency	Notes	Pic	Sev	HS	LT	Pts	Date	Fixed
Patio/Porch/Balcony	Ceiling	CRACK: Crack > 1/8in. wide and 11in. long	Repair damaged materials in between unit 103 and 104	<u>12</u>	L1			0.04	Dec 21 2018 9:14AM	
		9 Unit 104 T	otals							
Violations: 1	Possible Pts.: 1.4	4 Pts. Lost: 0.042 (0.042	2 Raw/0.042 Adj./0.04	42 Ca	ap)	Pts	s. Re	taineo	l: 1.358	
		Unit								
9 Unit 107	ltom	Deficiency	Notoo	D:-	0	110		D4-	Dete	E inter
Location	Item	Deficiency	Notes	PIC	Sev	HS	LI	Pts	Date	Fixed
Living Room	Windows	PANES: Cracked or broken window panes - no sharp edges	Repair or replace window near street	<u>13</u>	L1			0.04	Dec 21 2018 9:16AM	
		9 Unit 107 T	otals							

Inspection Photos

Entire Site




ہ Site Roads/Parking/Curbs - Roads/Parking/Curbs





1 Laundry Room - Accessories




1 Laundry Room - Windows


7 15 Unit 192 Patio/Porch/Balcony - Ceiling



10 5 Unit 39 Living Room - Windows



13 9 Unit 107 Living Room - Windows



8 20 Unit 277 Patio/Porch/Balcony - Ceiling



11 8 Unit 91 Patio/Porch/Balcony - Ceiling



9 4 Unit 19 Living Room - Windows



12 9 Unit 104 Patio/Porch/Balcony - Ceiling

Date 11/05/2019

Type Pre-REAC

Score 97

Area	*Pts.Lost(Raw)	*Pts. Lost(Adj.)	*Pts. Lost(Cap)	Poss. Points	Score	Violations
Site	1.91	1.91	1.91	15	13.09	1
Exterior	0.42	0.42	0.42	15	14.58	3
Systems	0	0	0	20	20	0
Common	0	0	0	15	15	0
*Units	0.06	0.06	0.06	35	34.29	2
Total	2.39	2.39	3.04	100	96.96	6

Pts. Lost (Raw) is the total point loss of all findings before the application of HUD scoring rules *Pts. Lost (Adj.) is the raw point loss adjusted for multiple findings of the same violation in the same building/unit per HUD rules* *Pts. Lost (Cap) is the adjusted point loss capped by the maximum possible point loss of each building/unit per HUD rules* *Units Area Score is projected for the REAC sample size based on the average unit score*

		Entire S	Site							
Site										
Location	Item	Deficiency	Notes	Pic	Sev	HS	LT	Pts	Date	Fixed
Roads/Parking/Curbs	Roads/Parking/Curbs	STRIPING: Faded or Missing Parking Lot Striping	Please restrip all faded fire lanes and parking spaces.						Nov 6 2019 3:02PM(LT)	
Roads/Parking/Curbs	Roads/Parking/Curbs	CRACKS: More than 10% of roadways affected by 3/4in. or greater cracks, settlement, or heaving	Please repair all potholes that are deep enough to cause vehicle hazards or damage	<u>1</u>	L2			1.91	Nov 5 2019 10:23AM(LT)	

Site Totals

Violations: 1 Possible Pts.: 15 Pts. Lost: 1.913 (1.913 Raw/1.913 Adj./1.913 Cap)

Pts. Retained: 13.088

			Exteri	or							l
10											
Location	Item	Deficiency		Notes	Pic	Sev	HS	LT	Pts	Date	Fixed
Entire Building	Entire Loca	Observation for Location that re order (See Note	quires a work	Repair broken window of building nine just to the right of entry door of unit 99	<u>2</u>					Nov 5 2019 10:37AM(LT)	
			10 Exterior	Totals							
	Violations: 0	Possible Pts.: 0.349	Pts. Lost:	0 (0 Raw/0 Adj./0 Cap)		Pts. F	Retair	ned:	0.349)	

			Ext	erior							
14											
Location	ltem	Def	iciency	Notes	Pic	Sev	HS	LT	Pts	Date	Fixed
Exterior Walls	Walls	CAU 12in.	LKING: Deteriorated ca	ulk < There's a hole in the exterior wall covering unit 180 of building 14 the corner right above the unit entry please ensure all exterior hole are repaired	in <u>3</u>	L1			0.11	Nov 5 2019 10:55AM(LT)	
			14 Exter	ior Totals							
Violations: 1	Possible	Pts.: 0.943	Pts. Lost: 0.105	(0.105 Raw/0.105 Adj./	0.105	Cap)	F	Pts. R	etaine	ed: 0.837	

		Exterio	r							
20										
Location	Item	Deficiency	Notes	Pic	Sev	HS	LT	Pts	Date	Fixed
Exterior Walls	Walls	CAULKING: Deteriorated caulk < 12in.	On the east side of the building second-floor above unit 270 there is a hole in exterior wall covering please ensure proper repairs are made	<u>4</u>	L1			0.11	Nov 5 2019 11:11AM(LT)	
Exterior Walls	Walls	CAULKING: Deteriorated caulk in area > 12in.	On the east side of building 20 above unit 265 there are two exterior wall covering holes please ensure holes are properly repaired	<u>5</u>	L2			0.21	Nov 5 2019 11:13AM(LT)	
		20 Exterior 1	otals							
Violations: 2	Possible Pts.: (16 Raw/0.316 Adj./0.3	816 C	(an)	Р	ts R	etaine	ed: 0.627	
					~P)	•				
		Unit								
5 Unit 33										
Location	ltem	Deficiency	Notes	Pic	Sev	HS	LT	Pts	Date	Fixed
Location Bedroom 1	Item Windows	Deficiency PANES: Cracked or broken window panes - no sharp edges	Notes Please repair broken window on the west side of building on bottom floor south end of building	<u>6</u>	Sev	HS	LT	Pts 0.04	Date Nov 5 2019 10:26AM(LT)	Fixed
		PANES: Cracked or broken window panes - no sharp edges	Please repair broken window on the west side of building on bottom floor south end of building			HS	LT		Nov 5 2019 10:26AM(LT	Fixed
	Windows	PANES: Cracked or broken window panes - no sharp edges 5 Unit 33 Te	Please repair broken window on the west side of building on bottom floor south end of building	<u>6</u>	L1			0.04	Nov 5 2019 10:26AM(LT	Fixed
Bedroom 1	Windows	PANES: Cracked or broken window panes - no sharp edges 5 Unit 33 T 1.4 Pts. Lost: 0.035 (0.035	Please repair broken window on the west side of building on bottom floor south end of building	<u>6</u>	L1			0.04	Nov 5 2019 10:26AM(LT)	Fixed
Bedroom 1 Violations:	Windows	PANES: Cracked or broken window panes - no sharp edges 5 Unit 33 To	Please repair broken window on the west side of building on bottom floor south end of building	<u>6</u>	L1			0.04	Nov 5 2019 10:26AM(LT)	Fixed
Bedroom 1 Violations: 8 Unit 92	Windows 1 Possible Pts.:	PANES: Cracked or broken window panes - no sharp edges 5 Unit 33 To 1.4 Pts. Lost: 0.035 (0.035 Unit	Please repair broken window on the west side of building on bottom floor south end of building otals 5 Raw/0.035 Adj./0.03	6 35 Ca	L1	Pts	s. Re	0.04	Nov 5 2019 10:26AM(LT)	
Bedroom 1 Violations:	Windows	PANES: Cracked or broken window panes - no sharp edges 5 Unit 33 T 1.4 Pts. Lost: 0.035 (0.035	Please repair broken window on the west side of building on bottom floor south end of building	6 35 Ca	L1	Pts	s. Re	0.04	Nov 5 2019 10:26AM(LT)	Fixed

8 Unit 92 Totals

Pts. Lost: 0.021 (0.021 Raw/0.021 Adj./0.021 Cap) Violations: 1 Possible Pts.: 1.4 Pts. Retained: 1.379

Inspection Photos

Entire Site




Site - Roads/Parking/Curbs Roads/Parking/Curbs - Please repair all potholes that are deep enough



Exterior



14 - Exterior Walls Walls - There's a hole in the exterior wall covering by unit 180



20 - Exterior Walls Walls - On the east side of the building second-floor above unit 270 t



 $\begin{array}{c} 5\\ 20\ \text{-} Exterior\ \text{Walls}\\ \text{Walls}\ \text{-}\ \text{On\ the\ east\ side\ of\ building\ }20\ above\ unit\ 265\ there\ are\ two\ e} \end{array}$

Unit





5 Unit 33 - Bedroom 1 Windows - Please repair broken window on the west side of building on

7 8 Unit 92 - Patio/Porch/Balcony Lighting - Please repair or replace exterior light in between unit 90